



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TP/acc Fraction

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM - SMRT			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 30/06/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	10/04/2017	SLM7550Y	0	62566	69DS/SLM7550Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3702009389		2NRX142609	60	Raymond Seah L M	28/06/2021 14.48		--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: 04/06/2021 10. 30 HRTP VEH:SHD6402T ACC DATE:03/06/2021 TP INS:SMRT NO OF REPAIR DAYS:03 DATE-IN:28/06/2021 DATE SURVEY:28/06/2021 BY:LKK-STEVE AUTHORISED ON:17/06/2021 -TP/DS CLAIM						30.00
2	S	BP-SUBLET TO RESET ECU AND REPROGRAMME R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION. TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.						180.00
3	S	BP-SUBLET TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIN ALL OTHER AFFECTED AREAS.						720.00
4	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.						590.00
5	1	K52159-0U908	COVER, RR BUMPER, L		1.00	526.00		526.00
6	2	K52161-0K040	PIECE, RR BUMPER		4.00	4.10		16.40
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							2,062.40	
			Please acknowledge receipt of vehicle		Parts		GST 7.00%	
					542.40		144.37	
					Labour			
					30.00			
					Sublet		Less	
1,490.00		0.00						
Lubrication/Fluid								
0.00								
Others		Amount Due						
0.00		2,206.77						

Company Copy

Vehicle Diagnostic Report

2NRFE
304772 km

MHFB29F3702009389

Borneo Motors

Printed By: Default User(1)

01/07/2021 1:46:30 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT	Yes	P1605	X		X		-	30DU2000	No
								A0202000	
Cruise Control							-	-	No
ABS/VSC/TRC							-	F15260D330	No
Air Conditioner							-	886500D65001	No
Combination Meter							-	838000US8003	No
SRS Airbag							-	8917F0D360	No
Immobiliser							-	-	No

Vehicle Diagnostic Report

2NRFE
304772 km

MHFB29F3702009389

Borneo Motors

Printed By: Default User(1)

01/07/2021 1:47:19 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT							-	30DU2000	No
								A0202000	
Cruise Control							-	-	No
ABS/VSC/TRC							-	F15260D330	No
Air Conditioner							-	886500D65001	No
Combination Meter							-	838000US8003	No
SRS Airbag							-	8917F0D360	No
Immobiliser							-	-	No