



Borneo Motors



TOYOTA

Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

clear

2P/12

ESTIMATE

Account Details				Customer Details			
THIRD PARTY CLAIM <i>liability check</i>				Account No.	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
				S1000020 / TPCLAIM			
				Document No.			
				0			
				Document Date			
				04/06/2021			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	10/04/2017	SLM7550Y	0	62566	69DS/SLM7550Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3702009389		2NRX142609	60	Raymond Seah L M	0.00		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: 04/06/2021 10. 30 HRTV VEH:SHD6402T ACC DATE:03/06/2021 TP INS:SMRT NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORIZED ON: -TP/DS CLAIM					30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					180.00
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.					122.40
4	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TEST FUNCTION.					180.00
5	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIN ALL OTHER AFFECTED AREAS.					2160.00
6	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.					1770.00
7	1	K81550-0D550 LAMP ASSY, RR COMBIN	1.00	319.70			319.70
8	2	K81560-0D550 LAMP ASSY, RR COMBIN	1.00	319.70			319.70
9	3	K81580-0D190 LAMP ASSY, RR, RH	1.00	189.30			189.30
10	4	K81590-0D150 LAMP ASSY, RR, LH	1.00	189.30			189.30
11	5	SPZ061-0D035 17 BACK SENSOR SILVER METALLIC	1.00	146.70			146.70
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy

Borneo Motors



TOYOTA

Reg No. : 196700086Z
 SST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details				Customer Details			
THIRD PARTY CLAIM				Account No.	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
				S1000020 / TPCLAIM			
				Document No. 0			
				Document Date 04/06/2021			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	10/04/2017	SLM7550Y	0	62566	69DS/SLM7550Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3702009389		2NRX142609	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
12	6	K52159-0U908 COVER, RR BUMPER, L	1.00	521.00	526	521.00	
13	7	K52161-0K040 PIECE, RR BUMPER	4.00	4.10		16.40	
14	8	K52575-0D240 RETAINER, RR BUMPER	1.00	120.10		120.10	
15	9	K52576-0D240 RETAINER, RR BUMPER	1.00	120.10		120.10	
16	0	K52155-0D090 SUPPORT, RR BUMPER S	1.00	23.10		23.10	
17	1	K52156-0D080 SUPPORT, RR BUMPER S	1.00	23.10		23.10	
18	2	K52023-0D100 REINFORCEMENT SUB-AS	1.00	332.70		332.70	
Stere CLKK) wr AL 28/6/21, 3.0pm P/P My Balry							
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplemental item(s) approval from Insurance Company				Charge Summary		Total 6,763.60	
For & on behalf of Borneo Motors (Singapore) Pte Ltd Acknowledged by Repairer				Parts 2,321.20 Labour 4,442.40 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 473.45 Less 0.00 Amount Due 7,237.05	

Company Copy