

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC3431J

Date: 08/06/21

Make : HYUNDAI

Insurance: AIG

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER FOG LAMP			\$201.50
	SUB TOTAL			\$1,134.15
	LESS 20%			\$226.83
	DISCOUNTED TOTAL			\$907.32
1	REAR BUMPER RUBBER MAT			\$50.00
1	REAR NUMBER PLATE WITH TRIM COVER			\$45.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
				\$225.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$300.00
	WIRING CHARGE			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	TOTAL LABOUR			\$830.00
	ESTIMATE TOTAL			\$1,962.32

x R
XSVL
- SCR
XSVL

- NEL
- CRK
XSVL

350
250
XWN
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAR LKIC
8/6/2021 1655
HP
2 Days
After repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: