

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

Our Job Ref No : 305472621
Date : 12/06/21

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. : SHC3431J CTPL

06.06.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- SMX7216T
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$841.12
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost** \$1,471.12
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed If there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : _____

Name : NAZ LKK

Date : 16/6/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 12.06.2021
Time: 10:19:00
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472621
REGN NO : SHC3431J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 02.07.2019
DATE/TIME IN : 07.06.2021 12:35
ACCIDENT DATE : 06.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NUMBER PLATE REAR WITH TR	1 N	45.00	2.00-	45.00	✓CRK
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	✓DEF
0003 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00	✓NEC
0004 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	✓DEF
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	✓NEC

SUB-TOTAL : 841.12

JOB NATURE

0000 PB	PANEL BEATING SHC3431J	350.00	✓
0001 SP	SPRAYPAINT CHARGE	250.00	✓
0002 20-204	REMOVE/REFIX REVERSE SENSOR	30.00	✓

SUB-TOTAL : 630.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 12.06.2021

Time: 10:19:00

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472621
REGN NO : SHC3431J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 02.07.2019
DATE/TIME IN : 07.06.2021 12:3
ACCIDENT DATE : 06.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,471.12

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

REPAIR ESTIMATE

Model : IONIQ(G3)

Insurance: AIG

MVA: MS. LOKE YY

~~X R~~ ^{OFF}
~~X JUL~~ ^{NEC}
 — SCR
 JUL

 — NEC
 — CRK
 X JUL

 350
 250
 X NN
 30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ UKIC
8/6/2021 1635
HP
2 DMS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: