



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2108713

INV Date 20/12/2021

Reference CC4/LPC21006509/Aga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SCH 8862Z
Insured Veh. SKT 9046Z
Claim No. 20/21/21/VP05/024633
Policy No. Z20VP05027015
Accident Date 07/06/2021
Inspection Date 16/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21006509/Aga3q2 Date: 20/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 9046Z	Veh. Inspected	SCH 8862Z	
Policy No.	Z20VP05027015	Coverage (\$)	0.00	
Claim No.	20/21/21/VP05/024633	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	08/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JM6GJ103100140870	Colour	GREY	
Odometer	112359 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	PIRELLI	6 mm	
L/H Front Tyre	245/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/06/2021	Inspection Date	16/06/2021	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCH 8862Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,230.00	1,230.00
2	REAR BUMPER SIDE HOLDER -LH/RH @\$41.00	NOT NECESSARY	82.00	-
10	REAR BUMPER CLIPS @\$4.80	NECESSARY	48.00	48.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	538.00	-
4	REAR BUMPER SENSOR @\$203.00	NOT NECESSARY	812.00	-
1	REAR BUMPER SENSOR WIRE	NOT NECESSARY	132.60	-
1	REAR BUMPER TOW COVER	MISSING	24.90	24.90
1	REAR BUMPER REFLECTOR -RH	NOT NECESSARY	53.00	-
1	REAR BUMPER BRACKET -RH	NOT NECESSARY	58.00	-
1	REAR PANEL	TO REPAIR SEE LABOUR	700.10	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	460.00	-
1	REAR PANEL LOCK SENSOR	NOT NECESSARY	142.00	-
1	REAR BOOT	DENTED	1,413.00	1,413.00
1	REAR BOOT OUTER GARNISH WITH CHROME	NOT NECESSARY	890.00	-
1	REAR BOOT TOP LOCK	DAMAGED	287.00	287.00
1	REAR BOOT BOTTOM LOCK	NOT NECESSARY	46.00	-
1	REAR BOOT RUBBER	NOT NECESSARY	147.00	-
1	REAR BOOT MAZDA LOGO	NECESSARY	49.00	49.00
1	REAR BOOT MAZDA 6 LOGO	NECESSARY	23.00	23.00
1	REAR BOOT SKYACTIV LOGO	NECESSARY	74.00	74.00
1	REAR EXHAUST PIPE WITH CHROME	NOT NECESSARY	1,750.00	-
	LESS 20% DISCOUNT		-1,791.92	-629.78
			7,167.68	2,519.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	35.00	-
1	REAR BOOT CAMERA (SN)	NOT NECESSARY	350.00	-
2	SEALANT @\$20.00 (SN)	NECESSARY	40.00	40.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER SENSOR (SN)	DAMAGED	220.00	200.00

Report Ref No. CC4/LPC21006509/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CAR DECAL (REAR BOOT,REAR BUMPER)(SN)	NECESSARY	1,200.00	300.00
			1,865.00	560.00
	LABOUR			
	TO KNOCK OUT DENTS ,REPAIR REAR FLOOR PANEL,REMOVE,CUT/WELD REAR PANEL ,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR PANEL .		800.00	500.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		800.00	500.00
	TO CHECK WIRING .		50.00	30.00
	TUFFKOTE.		60.00	40.00
	TO REMOVE ,TRANSFER REAR BUMPER SENSOR .		100.00	50.00
	TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR.		150.00	60.00
	TO REMOVE,REPLACE REAR EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TO REMOVE,REFIX REAR WINDSCREEN TO FACILITATE REPAIR.		150.00	120.00
	TO TRANSFER REAR BOOT FITTING.		80.00	80.00
			2,270.00	1,380.00
GRAND TOTAL			11,302.68	4,459.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,550.00

Report Ref No. CC4/LPC21006509/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCH 8862Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCH 8862Z

RE-INSPECTION

