

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : FOO CHIK NEE @ FOO CHIK ENG
 32 TANAH MERAH KECHIL ROAD #07-16
 EAST MEADOWS S(465559)

Estimate No: **EST1507009**
 Date: 07 Jun 2021
 Policy No: GA143588
 Veh Reg No: **SCH8862Z**
 Make/Model: MAZDA MAZDA6
 WAGON 2.5 A/T ABS
 D/AIRBAG 2WD SR
 Chassis No: JM6GJ103100140870
 Engine No: PY20417482
 Reg. Date: 19/12/2014

ATTN:

Your Ref No: TP 0621-6392
 Claim Type: Third Party
 Accident Date: 07/06/2021
 TP Veh Reg No: SKT 9046 Z

TP Lon Pac.
 Cecilia.

Estimate Repair Cost to Vehicle No :SCH8862Z

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BUMPER <i>Replaced</i>	1,230.00	1 PC	1,230.00 ✓	
2 REAR BUMPER SIDE HOLDER - LH/RH <i>new</i>	41.00	2 PC	82.00 +	
3 REAR BUMPER CLIPS <i>new</i>	4.80	10 PC	48.00 ✓	
4 REAR BUMPER REINFORCEMENT <i>new</i>	538.00	1 PC	538.00 +	
5 REAR BUMPER SENSOR <i>Replaced 2 pieces new</i>	203.00	4 PC	812.00 426.4	
6 REAR BUMPER SENSOR WIRE <i>new</i>	132.60	1 PC	132.60 +	
7 REAR BUMPER TOW COVER <i>Missing</i>	24.90	1 PC	24.90 ✓	
8 REAR BUMPER REFLECTOR - RH <i>new</i>	53.00	1 PC	53.00 +	
9 REAR BUMPER BRACKET - RH <i>new</i>	58.00	1 PC	58.00 +	
10 REAR PANEL <i>Repair</i>	700.10	1 PC	700.10 +	
11 REAR PANEL TOP GARNISH <i>new</i>	460.00	1 PC	460.00 +	
12 REAR BOOT LOCK SENSOR <i>new</i>	142.00	1 PC	142.00 +	
13 REAR BOOT <i>Dented</i>	1,413.00	1 PC	1,413.00 ✓	
14 REAR BOOT OUTER GARNISH WITH CHROME <i>new</i>	890.00	1 PC	890.00 +	
15 REAR BOOT TOP LOCK <i>Damaged</i>	287.00	1 PC	287.00 ✓	
16 REAR BOOT BOTTOM LOCK <i>new</i>	46.00	1 PC	46.00 +	
17 REAR BOOT RUBBER <i>new</i>	147.00	1 PC	147.00 +	
18 REAR BOOT MAZDA LOGO <i>new</i>	49.00	1 PC	49.00 ✓	
19 REAR BOOT MAZDA 6 LOGO <i>new</i>	23.00	1 PC	23.00 ✓	
20 REAR BOOT SKYACTIV LOGO <i>new</i>	74.00	1 PC	74.00 ✓	
21 REAR EXHAUST PIPE WITH CHROME <i>new</i>	1,750.00	1 PC	1,750.00 +	
			8,959.60	
		Less 20%	1,791.92	7,167.68
Special Net				
22 REAR NUMBER PLATE WITH CASING <i>new</i>	35.00	1 PC	35.00 +	
23 REAR BOOT CAMERA <i>new</i>	350.00	1 PC	350.00 +	
24 SEALANT <i>new</i>	20.00	2 PC	40.00 ✓	
25 SPONGE TAPE <i>new</i>	20.00	1 PC	20.00 ✓	
26 REAR BUMPER SENSOR <i>Damaged</i>	220.00	1 SET	220.00 220.00	
27 CAR DECAL (REAR BOOT, REAR BUMPER) <i>new</i>	1,200.00	1 PC	1,200.00 1,200.00	
			1,865.00	1,865.00
Labour				
28 TO KNOCK OUT DENTS, REPAIR REAR FLOOR PANEL, REMOVE, CUT/WELD REAR PANEL, REPLACE ACCIDENT PARTS	800.00	1 JOB	800.00 800.00	

3148.50

2519.12

S60

500

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : FOO CHIK NEE @ FOO CHIK ENG
 32 TANAH MERAH KECHIL ROAD #07-16
 EAST MEADOWS S(465559)

ATTN:

Your Ref No: TP 0621-6392
 Claim Type: Third Party
 Accident Date: 07/06/2021
 TP Veh Reg No: SKT 9046 Z

Estimate No: **EST1507009**
 Date: 07 Jun 2021
 Policy No: GA143588
 Veh Reg No: **SCH8862Z**
 Make/Model: MAZDA MAZDA6
 WAGON 2.5 A/T ABS
 D/AIRBAG 2WD SR
 Chassis No: JM6GJ103100140870
 Engine No: PY20417482
 Reg. Date: 19/12/2014

Estimate Repair Cost to Vehicle No :SCH8862Z

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
29 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.00	1 JOB	800.00 500	
30 TO CHECK WIRING	50.00	1 JOB	50.00 30	
31 TUFFKOTE	60.00	1 JOB	60.00 40	
32 TO REMOVE, TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	100.00 50	
33 TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	150.00	1 JOB	150.00 60	
34 TO REMOVE, REPLACE REAR EXHAUST PIPE	80.00	1 JOB	80.00	
35 TO REMOVE, REFIX REAR WINDSCREEN TO FACILITATE REPAIR	150.00	1 JOB	150.00 120	
36 TO TRANSFER REAR BOOT FITTING.	80.00	1 JOB	80.00	
			2,270.00	2,270.00

Total S\$ 11,302.68

Add GST @ 7% 791.19

Total Amount Payable S\$ 12,093.87

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND NINETY THREE AND CENTS EIGHTY SEVEN ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4459.12 Adrian

L/S: 3550. 2/s 16/06/21

07 Pays.
(studies).