(08/11/13) wef	per 101 ac	a stage to
ASS. REC. BY: March	REF: 05/ 27/	21006511/4vc
`	ASSI	GNMENT
From:	Date:	Veh No: 637 4910 X Yr Regn: 30/14/19
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD) TP / WS / TP RES / OD RI	ES / EVA / INV / MV	Truck / Trailer or CA/
	•	Make: Toyoto hiace c.c 275-4
at Workshop m/s	abj 4910 X	Make: Toyoto Viace cc 275-4 Colour Silver A/C: Insured/Std/NI/NA
of		Sp.Reading 127 4 T/Radio: Insured / Std / NI / NA
Insured:		Eng/No:
Policy No.		C/No: GDH 201200 3906
Claims No.		Gen. Cond: 800d / Fair / Poor / Burnt
Sum Insured:	Excess: \$SVO	Steering: Increer / Jammed / Leaked / Burnt or
(Client's Record)		Brake: Increar / Jammed / Leaked / Burnt or
Make of Veh:		Modi: (Nil) S/Rim / STD A/Rim or
	_	Tyre Size: F: 195~15
(Policy Condition)		R:
Remark: The veh had comme	enced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of	,	OYO / YOKO or
Bal. or Market Value:	\$ 6UL.	Front Rear
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen:	Consistent?: Yes or No	D.O.A. \$\int \( \begin{array}{ccccc} \limin & \l
Est. Repairs:	days Res.: Yes or No	D.O.A. 5/6/2/ D.O.I. 10/6/2/
Lum Sum:	% 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24	HRS S Vehicle YN BUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
O	Vehicle: 9N/ OUT	
Duto.	LTH IT VIVO	
Date / Time Action / Inst	truction Dep 8000 D headlamp (11+4000?	
711		
	•	T. Of Bassin
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:  Resurvey No. of Trip: Survey Fee:
1)	: Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
Date/Time, File Return to?	Add Fe	
ra's		1

: Interview (\$

: Tech. Invs (\$

:Weekend (\$

) Photos

) Others

TOTAL

2)

Report Format :

Lump Sum / I.B.I: (\$

## Jin Auto Services Pte Ltd #01-410/412, 14 Defu Lane 10 539195

Insurer Reference: GBJ4910X Repairer Reference: GBJ4910X

Date calculated: 08/06/2021 1:02 PM

**Full Report** Registration: GBJ4910X Printed: 08/06/2021 1:02 PM

## **Summary Information**

Claim

Singapore (SG) Location:

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

Printed by: Claim Reference: 10UIS SEOW GBJ4910X

SGD 05/06/21

Estimated Repair Time: Actual Repair Days:

Date of Incident: Hire Car Start: Hire Car End:

Currency:

#### **Vehicle Details**

Vehicle

Manufacturer:

TOYOTA HIACE

Model: Sub Model:

BASE MODEL 70 E4 01

Model Sheet Number: Registration:

GBJ4910X 1GD8353299

VIN number: Odometer:

Model Specs

FROM 01.2018

WHEELBASE 2570MM TWO COAT METALLIC

L/CTR SLDG WINDOW L/SLIDING DOOR PREPARE OFF VEHICLE R/CTR SLDG WINDOW R/SLIDING DOOR

2.8 LTR 130KW

VERS GEN COUNTRIES

### Vehicle Condition

Vehicle Status

Pre-Accident Damage:

Date of Inspection:

#### **Damage Areas**

ΔII Underbody




LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



#### Labour

Labour	Time Base 10 WU/h	D	rico - 42 (	00 SGD/h
Codo		P		Price SGD
Code	Description		WU	Price 3GD
B091	R + R RIGHT FRONT WING		1.0	4.20
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	12.60
B020	RENEW FRONT BUMPER		7.0	29.40
	(RADIATOR GRILLE REMOVED)			
	INCLUDES: FRONT BUMPER AND REQUIRED			
	ATTACHED PARTS R + R			
NO NUMBER	R + R R/F BUMPER MOUNTING		1.0	4.20
B030	R + R RADIATOR GRILLE		2.0	8.40
B040	R + R RIGHT HEADLAMP		3.0	12.60
	(BUMPER REMOVED)			
	INCLUDES: ADJUST HEADLAMPS.			
B210	RENEW RIGHT FRONT DOOR		23.0	96.60
	INCLUDES: R + R AND ALIGN RIGHT FRONT			
	DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF			
	NECESSARY			
B210)	RENEW R/DOOR HINGES		1.0	4.20
171011	RENEW AIR CLEANER ELEMENT		1.0	4.20
2146	R/F STEP REPAIR	10	20.0*	84.00
2228	RIGHT A-PILLAR REPAIR	20	50.0*	210.00
4251	FRONT FLOOR PANEL REPAIR		30.0*/	126.00
1000	DOOR HARNESS RH DOOR HARNESS	20	40.0*	168.00
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	18.20	182.0	764.40
	Total of Labour			764.40

#### Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLEC	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	RIGHT FRONT DOOR NEW PART PAINTING	17.0
	FRONT BUMPER NEW PART PAINT K1G	23.0
	RIGHT A-PILLAR REPAIR PAINTING <50%	12.0
	R/F STEP SURFACE PAINT	4.0
	FRONT FLOOR PANEL SURFACE PAINT	7.0

#### **Paint Material Per Part**

Code	Description	Price SGD
0331	FRT BUMPER SUPPORT SURFACE PAINT	4.48
1482	RIGHT FRONT DOOR NEW PART PAINTING	49.02
0281	FRONT BUMPER NEW PART PAINT K1G	76.55
2228	RIGHT A-PILLAR REPAIR PAINTING <50%	16.15
2146	R/F STEP SURFACE PAINT	3.49
4251	FRONT FLOOR PANEL SURFACE PAINT	15.44

Labour Cost - Paint	43.00 CCD /h	Hrs	wu	Price SGD
Factor Time Paint	42.00 SGD/h		67.0	
		2.50		405.00
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	10.00	100.0	420.00
Material Cost - Paint				Price SGD
New Part Painting				49.02

New Part Painting New Part Painting - Plastic K1G 76.55 Repair Painting 16.15 Surface-/Blend Paint 23.41 Material-constant Metal Preparation 28.60 Material-constant Plastic 12.70

**Total** 

## **Spare Parts**

				prices as at 2	015-06-01/01
Code	Description	Part Number	Part Sou	irce	Price SGD
0254	R/F BMPR BLANK CAP	53112 26060	Original	6	40.00
0281	FRONT BUMPER	52119 26651	Original	205	180.00
0318	R/F INNER COVER BRKT	52115 26170	Original	cu-	60.00
0331	FRT BUMPER SUPPORT	52131 26021	Original	?	115.00
0562	RIGHT HEADLAMP ASSY	81130 26731	Original	che v	400.00
1482	RIGHT FRONT DOOR	AGENT	Original	Level /	1,100.00
1496	R/F LOWER DOOR HINGE	68730 26012	Original	?	45.00
2194	R/F STEP TRIM garnish	51773 26023	Original	Dis -	75.00
8395	AIR FILTER ELEMENT	17801 30070	Original	Brow	370.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal				0.00 2,385.00
a. coop pures	Total				2,385.00

## **Extras**

Code	Description	Pr	ice SGD
1001	DOOR BLACK STICKER DOOR STICKER	nec	15.00*
	Total Extras		15.00

206.43

2,385.00

#### Final Calculation

Labour Time Base 10 WU/h

Total 182.0 WU X 42.00 SGD/h

Paint Work Time Base 10 WU/h

**Total Paint Including Material** 

**Repair Cost Excludes GST** 

**Repair Cost Included GST** 

Labour Cost 100.0 WU X 42.00 SGD/h

Audatex System Using Manufacturer Times

**Parts** 

**Total Parts** 

**Total of Labour** 

**Total Of Extras** 

Material Cost

GST (+7.00%)

Comments * - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS
Assessment Note
No assessment notes entered.

Page 4 of 4

SGD

2,385.00

764.40

15.00

626.43

3,790.83

4.056.19

PRINT DATE 08/06/2021

265.36

SGD

2.385.00

764 40

420.00

206.43

# > Back to OneMotoring

## **Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Business
wner ID:	842B
ehicle Details	
ehicle No.:	GBJ4910X
/ehicle to be Exported:	No
ntended Deregistration Date:	09 Jun 2021
/ehicle Make:	TOYOTA
/ehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1GD8353299
Chassis No.:	GDH2012003906
Maximum Power Output:	-
Open Market Value:	\$37,009.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Fransfer Count:	1
Actual ARF Paid:	\$1,851.00
ntended PARF Rebate Details	N
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
ntended COE Rebate Details	29 Apr 2029
OE Expiry Date:	C - Goods Vehicle & Bus
OE Category:	
COE Period(Years):	10
PQP Paid:	\$19,728.00
COE Rebate Amount:	\$15,563.00
Total Rebate Amount:	\$15,563.00

The information contained herein is correct as at 09 Jun 2021

OK

