

ASS. REC. BY:

REF:

TP / CS/TP21006516/Kuc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/HS/TP RES/OD RES/EVA/INV/INV

To inspect Vehicle No: WP0ZZZ98ZLS220111

at Workshop no's

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Lantern

Veh No:

220111

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche 718 Boxster

Colour:

M. Grey

Sp. Reading

Eng/No:

C/No:

WPO 7779 8 ZLS 220111

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35 ZR20

R:

265/35 ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

27/5/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front and N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Battery Flat (Veh imported from England)
 The Surveyor's report is for custom used and not for claim, so
 no GIA report.
 They will prepare cheque when report is ready.

Date/Time, File Pass to?

☐

: Prel. Report

1) 9/6 TYPIST

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 66,763.81



Carakaunsi Leasings Pte Ltd
1 SOON LEE ST PIONEER CENTRE #02-48 S627605
TEL: 63394498

Not Authorized

Repair Estimates

WP0ZZZ98ZLS220111

Parts (a) Cost / List Price Items	\$	90,339.31
Plus/Less 10%	\$	9,033.93
Total of Cost / List	\$	81,305.38
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items		
Total Parts Cost		
Labour	\$	6,410.00
Total	\$	87,715.38

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenrick

Company

:

LKK

Survey conducted on

:

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



Car Council Leasings Pte Ltd
1 SOON LEE ST PIONEER CENTRE #02-48 S 627605
TEL: 63390498

Spare Parts

Vehicle No. : **TBA**
Make & Model : **PORSCHE 71S BOXSTER GTS 2.5 PDK**
Chassis No. : **WP0ZZZ98ZLS220111**

Submit By : **THOMAS MAH**
Year Manufacture : **2019**
Engine No. : **002241**
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front Fender <i>LH</i>	<i>Ry</i> 1	\$1,911.00	\$1,911.00	<i>/</i>
2	Front Bumper	<i>mi</i> 1	\$6,382.04	\$6,382.04	<i>/</i>
3	Front Bumper Spoiler	<i>mi</i> 1	\$1,242.60	\$1,242.60	<i>/</i>
4	Front Bumper Support Brackets	<i>mi</i> 4	\$22.06	\$88.24	<i>/</i>
5	Rear Bumper	<i>CM</i> 1	\$5,223.26	\$5,223.26	<i>/</i>
6	Rear Fender LH Side	<i>Ry</i> 1	\$1,844.26	\$1,844.26	<i>/</i>
7	Door LH Side	<i>Ry</i> 1	\$3,935.23	\$3,935.23	<i>/</i>
8	Headlamp Washer Unit & Retainer Plate supply	<i>mi</i> 2	\$236.04	\$472.08	<i>/</i>
9	18 nuts, 18 screws, 4 Sill Rings Parkin Sensors	<i>mi</i> 1	\$145.08	\$145.08	<i>/</i>
10	Front Bumper Grilles (5 pieces)	<i>mi</i> 1	\$1,539.34	\$1,539.34	<i>/</i>
11	Plastic Bumper Trims (3 pieces)	<i>mi</i> 1	\$391.34	\$391.34	<i>/</i>
12	2x Air Guide (Connect Radiator to Bumper)	<i>mi</i> 2	\$265.82	\$531.63	<i>/</i>
13	Centre Air Guide (water Radiator to bumper)	<i>CM</i> 1	\$317.51	\$317.51	<i>/</i>
14	Outside Temperature Sensor Indicator	<i>mi</i> 1	\$189.72	\$189.72	<i>/</i>
15	Foam Padding for Front Bumper Crash Bar	<i>mi</i> 1	\$84.63	\$84.63	<i>/</i>
16	4 x Front Parking Sensors	<i>mi</i> 4	\$412.64	\$1,650.56	<i>/</i>
17	Side Sill Cover	<i>mi</i> 1	\$1,045.54	\$1,045.54	<i>/</i>
18	Side ventilation unit	<i>CM</i> 1	\$335.17	\$335.17	<i>/</i>
19	Sill frame	<i>R and</i> 1	\$665.36	\$665.36	<i>X</i>
20	PDLS Plus Headlamp Unit <i>discm n/s Bro</i>	2	\$6,700.88	\$13,401.77	<i>/</i>
21	Front Fog Lamps	<i>mi</i> 2	\$820.07	\$1,640.15	<i>/</i>
22	Side indicator Lamps	<i>mi</i> 2	\$178.56	\$357.12	<i>/</i>
23	Front Wheel Arch Covers	<i>mi</i> 2	\$446.33	\$892.66	<i>/</i>
24	Rear Wheel Arch Covers	<i>mi</i> 2	\$433.72	\$867.44	<i>/</i>
25	Front Axle Wishbone - PASSENGER SIDE	<i>Ry</i> 1	\$1,413.60	\$1,413.60	<i>/</i>
26	Front Axle Tracking Arm - PASSENGER SIDE	<i>mi</i> 1	\$956.04	\$956.04	<i>/</i>
27	Rear Axle Wishbone - PASSENGER SIDE	<i>Ry</i> 1	\$1,225.26	\$1,285.26	<i>/</i>
28	Rear Axle Track Rod - PASSENGER SIDE	<i>Ry</i> 1	\$632.40	\$632.40	<i>/</i>



Car Connell Leasing Pte Ltd
1500H LEE ST PIONEER CENTRE #02-48 S627605
TEL: 63390498

Spare Parts

Vehicle No. : **TBA**
Make & Model : **PORSCHE 718 BOXSTER GTS 2.5 PDK**
Chassis No : **WP0ZZZ98ZLS220111**

Submit By : **THOMAS MAH**
Year Manufacture : **2019**
Engine No. : **002241**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
29	Front Absorber Set <i>BT</i>	1	\$2,688.36	\$2,688.36	✓
30	Rear Absorber Set <i>BT</i>	1	\$2,256.88	\$2,256.88	✓
31	Front Disc Rotors <i>Sn</i>	1	\$1,456.25	\$1,756.25	X
32	Rear Disc Rotors <i>Sn</i>	1	\$1,256.36	\$1,556.36	X
33	Fuel Pump <i>Sn</i>	1	\$5,856.36	\$5,856.36	X
34	1x Battery <i>Sn</i>	1	\$767.25	\$767.25	✓
35	1x Complete Water Radiator Unit (PASSENGER SIDE) <i>BT</i>	1	\$2,216.38	\$2,216.38	✓
36	1x Central Radiator <i>BT</i>	1	\$846.30	\$846.30	✓
37	1x Complete Water Radiator Unit (DRIVER SIDE) <i>BT</i>	1	\$2,216.38	\$2,216.38	✓
38	Condenser Units <i>BT</i>	2	\$1,243.04	\$2,486.08	✓
39	Door Handle <i>mi</i>	1	\$315.16	\$315.16	✓
40	Door Handle Mounting Bar <i>mi</i>	1	\$380.93	\$380.93	✓
41	Complete Mirror unit (PASSENGER SIDE) <i>mi</i>	1	\$2,772.67	\$2,772.67	✓
42	Complete Undertray Panel Set <i>mi/cmt</i>	1	\$2,904.39	\$2,904.39	✓
				\$60,000.01	
				\$78,460.78	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Car Council Carkaunsl Leasings Pte Ltd
1 SOON LEE ST PIONEER CENTRE #02-48 S627605
TEL: 63390498

Labour

Vehicle No. : **TBA**
Make & Model : **PORSCHE 718 BOXSTER GTS 2.5 PDK**

Submit By : **THOMAS MAH**
Year of Manufacture : **2019**

S/No	Labour Description	Estimated	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE WELL PANEL)	\$1,800.00	1600/-
	<i>under carriage</i>		
2	TO PERFORM MECHANICAL REPAIR AND REPLACE ENGINE AND MECHANICAL PARTS	\$2,200.00	1200/-
3	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE WELL PANEL)	\$1,600.00	1500/-
4	TO CHECK WIRING.	\$120.00	100/-
5	TO REMOVE AND REFIT SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	\$150.00	✓
6	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	\$120.00	✓
7	SUPPLEMENTARY LABOUR TO KNOCK OUT AND ADJUST CHASSIS BRACKET	\$180.00	150/-
8	REMARKS: TO DO TROUBLESHOOTING ON WIRING AND MECHANICAL PARTS ON ENGINE NOT ABLE TO START.	\$240.00	180/-
		\$6,410.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.