



簡福星摩王廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

DATE : 08-06-2021

VEHICLE NO. : SJX1028U
ACCIDENT DATE : 07-06-2021 17:18
THIRD PARTY REF. : GZ9115Z

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SJX1028U LEXUS ES250 LUXURY AUTO

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER	895.00 <i>del</i>
2	1	REAR BUMPER FOAM	145.70 <i>X ny</i>
3	1	REAR BUMPER REINFORCEMENT	621.00 <i>X ny</i>
4	2	REAR BUMPER SENSOR@\$488.00 <i>photo 313</i>	626 <i>616</i> 976.00 <i>nn ✓</i>
5	4	REAR BUMPER SENSOR RING@\$19.20	76.80 <i>na</i>
6	48	REAR BUMPER SENSOR BRACKET@\$21.30	0.00 <i>X nn</i>
7	10	REAR BUMPER CLIP@\$5.00	50.00 <i>new</i>
			<u>1637.80</u>
			2,764.50
			LESS 25 %
			691.13
			TOTAL (A) <u>1228.35</u>
			2,073.38
LABOUR CHARGES			
1	1	TO CHECK WIRING SYSTEM	30.00 ✓
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI-TTING NEW PARTS	400.00 <i>250</i>
3	1	SPRAYPAINTING CHARGES	400.00 <i>250</i>
			<u>1228.35</u>
			530
			1758.35
			2 days.
			830.00 <i>530</i>
			ESTIMATE TOTAL
			2,903.38

Taufik 97495749 / 62563561

'WP' 16/6/21 @ 115 pm

taufik e/khantowm.

02 days

H/S Resurvey after repair

P/P Resurvey before paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: