



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006528/Auf3n2	
			Date: 22/07/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 852C	Veh. Inspected	SLB 1717G
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/21/2016	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	09/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA C-HR HYBRID	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NMTKZ3BXX0R027390	Colour	SILVER
	Odometer	163395 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/06/2021	Inspection Date	09/06/2021
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	