

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG LI ENG
BLK 393 YISHUN AVE 6 #09-116
SINGAPORE 760393

Contact : 86871221, 92293432

TPSMRT.
Hui Zhen

ESTIMATE

Repair Code : CLM16839

Date in : 08/06/2021

Vehicle Num. : SLB1717G

Model : TOYOTA C-HR HYBRID 1.8 CVT

Chassis/Eng# : NMTKZ3BXX0R027390/2ZRV458368

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER (LOWER) <i>delud</i>	1	397.60	✓ 397.60
REAR BUMPER (TOP) <i>torn</i>	1	690.00	✓ 690.00
REAR BUMPER CENTER LAMP <i>could</i>	1	329.20	✓ 329.20
REAR BUMPER REFLECTOR GARNISH RH <i>could</i>	1	187.00	✓ 187.00
REAR BUMPER REFLECTOR RH <i>new</i>	1	59.00	x 59.00
REAR BUMPER REINFORCEMENT <i>delud</i>	1	352.70	✓ 352.70
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	112.20	x 224.40
REAR BUMPER TOW HOOK COVER <i>delud</i>	1	27.70	✓ 27.70
REAR END PANEL <i>Repair</i>	1	731.35	x 731.35
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	106.00	x 106.00
Subtotal before discount			3,104.95
Percentage discount 25%			776.24
Sub-total 1			2,328.71
REAR BUMPER CLIPS <i>new</i>	1	80.00	30 80.00
REAR BUMPER REVERSE SENSOR <i>damaged</i>	1	280.00	20 280.00
Subtotal before discount			360.00
Percentage discount 0%			0.00
Sub-total 2			360.00
Parts-total			2,688.71

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG LI ENG
BLK 393 YISHUN AVE 6 #09-116
SINGAPORE 760393

Contact : 86871221, 92293432

ESTIMATE

Repair Code : CLM16839

Date in : 08/06/2021

Vehicle Num. : SLB1717G

Model : TOYOTA C-HR HYBRID 1.8 CVT

Chassis/Eng# : NMTKZ3BXX0R027390/2ZRV458368

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

700	50	80.00
	X	80.00
	400	800.00
	250	800.00
	+	100.00
Labour Total		1,860.00
Parts & Labour Total		4,548.71

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
2/s 09/06/21.

03 Days.

Total: 241815

2/s 1.9K ✓