



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21006529/Uqf3n2	
			Date: 18/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 6854C	Veh. Inspected	SLK 3466U	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101470/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	09/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA GLS OPC (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMHU218319	Colour	BLUE	
Odometer	71939 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TOURADOR	6 mm	
L/H Front Tyre	195/65 R15	TOURADOR	6 mm	
R/H Rear Tyre	195/65 R15	TOURADOR	6 mm	
L/H Rear Tyre	195/65 R15	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND N/S FRONT PORTION.THE CAUSE OF DAMAGED DUE TO FALLEN OBJECT. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2021	Inspection Date	14/06/2021	
Survey held at	NINETEEN AUTOWERKS PTE. LTD. 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	