Messages

Claims



General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ra	tio	Parts & Labour	Miscellaneous	
		Summary						
General Details			Wo	Workshop Details				
nvolving	TPVD HONDA AIRWAVE (SGX372S)			al Rebate	0			
Date of Loss	7 June	7 June 2021		Amount				
ime of Loss	12:45		Net	t Loss Amount		-\$27,947.00		
oss Description	SHA4255E (INSD) SWERVED LEFT TO AVOID BUT STILL HIT REAR LEFT OF SGX372S (TP)		733	Assigned Workshop		LKK AUTO CONSULTANTS PTE LTD (TP)		
	WHICH	l STOPPED.		s of work		20		
Comment			con	npletion *				

Messages

Claims



General & Workshop	Details Ve	ehicle & Driver Details	Vehicle C	Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summar	у				
/ehicle & Driver De	tails							
/ehicle Registration#	SGX372S			Pur	chase Date	DD/MM/YYYY		
Registration State	SINGAPO	RE		Reg	istration Date *	08/08/2007		ı
Mileage	389179			Age	of Vehicle	13		
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMAT	ΓΙΟΝ	Dri	ver Details			
Manufacturing Year		2007		(CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
				[Oriver Name	TAY SOON JOO		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	TPVD HONDA	HONDA	Date of Birth	1 January 1999	DD/MM/YYYY
Model	AIRWAVE	AIRWAVE 1.5 A	Age	22	
Туре		v	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		GJ11126481	Driving Experience	0	
Engine No		L15A5181770	Driver License #		
Engine Capacity		1496	License Type		•
Sum Insured		0	License Issue Date		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	
Market Value		0	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	SG, Singapore	
Address type	Personal Correspondence	~
Gender	Unknown	~
Marital status	Unknown	•
Identification #	ТВС	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous			
			Summary					
Detailed Assessment		Со	Condition of Vehicle at time of survey					
Inspection Date *	10/06/2021		neral condition	Good		~		
Total Loss	Yes No	Ste	ering (Serviceable)	Yes	No			
Towing Charges	0		otbrake rviceable)	Yes	No			
Voluntary Excess	0		ndbrake rviceable)	Yes	No			
Compulsory Excess	0	Eng	gine Modification	Yes	No			
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	-accident condition	Good		~		

0

Tyre Condition

Age of Tyres	
Front Tyre Size	205/45R15
Front left side	FIRENZA8mm
Front right side	FIRENZA8mm
Spare wheel	
Rear Tyre Size	205/45R15
Rear left side	FIRENZA8mm
Rear right side	FIRENZA8mm

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous		
				Summary			
Tax Eligibility & Additi	onal Deduction for Parts						
Depr./Bttr%	0	Salv	Salvage%		0		
Discount%	20	Sett	lement%	100	100		
		Paint La	abour/Material F	Ratio			
Paint Labour Ratio	20	Cas	h Loss	Yes	No		
Paint Material Ratio	80	Part	Supplied by AXA	Yes	No		
					Save		

Messages

Claims



Add		Approve	Deny	Submi	t All							
EDIT	SR NO	QUAN MATERIAI	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTA PARTS	RY DEPR., BTTR%		SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1	REAR N/S TAIL- LAMP ASSY	Cut	0	487.1	No	0	20	0	0	389.68
	0	1	REAR BUMPER	Buckled	0	1078.5	No	0	20	0	0	862.8
	0	1	REAR N/S BUMPER SIDE RETAINER	Damaged	0	55.1	No	0	20	0	0	44.08
ır												
Add		Approve	Deny	Submit	All							
EDIT	SF		PART NAME		ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	PAINT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE	
	0		REMOVE / RENEW PARTS INCLUDING AND RESHAPE RE	KNOCKING	0	280	0	0	Reviewing			

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	0	400	0	0	Reviewing		
	0		CHECK / RECONNECT WIRING	0	20	0	0	Reviewing		
	0		TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	0	0	0	0	Deny		

Messages

Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add		Approve		Deny	Submit A	All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 3 DAYS	Reviewing	0	0		
	0	REAR REVERSE SENSOR	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR BUMPER CLIP (10PCS)	Reviewing	0	20	NECESSARY	



Messages

Claims



Assessment Details

General & Workshop Detai	ls Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary					
Estimated Claim \$0 Amount	0.00	Ad	justed Claim Amour	nt \$2,016.56	
CATEGORY	ESTIMATE	ADJUSTED			
Spare Parts	\$0.00	\$1,296.56			
Labour	\$0.00	\$700.00			
Miscellaneous	\$0.00	\$20.00			

Submit for Review



Messages


Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary					
Estimated Claim \$0.0 Amount	00	Adj	usted Claim Amoun	t \$1,600.00	
CATEGORY	ESTIMATE	ADJUSTED			
Miscellaneous	\$0.00	\$1,600.00			

Submit for Review