

Lian Her Motor Works

Blk 5034 #01-337 Ang Mo Kio Industrial Pk 2 Singapore 569537
H/p 91082728

Fax : 64816131

Lim Ji Hwee
Blk 809B Woodlands Dr 50
#06-293
Singapore 732890

Vehicle No : SMX 4446 R
Make : Toyota Vios
Year : 2021

Amendment copy

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear o/s fender			R	\$965.70	X
2 pcs	Rear fender inner trim	ok em photo	\$387.60	na	\$775.20	471.60
1 pc	Rear windscreen moulding			R1	\$95.10	X
1 pc	Rear boot lid			1m	\$786.20	✓
2 pcs	Rear boot lid reflector		\$370.20	RU	\$370.20	X
1 pc	Rear boot lid inner lock			CM	\$205.70	✓
1 pc	Rear boot lid inner lock sensor			na	\$185.70	✓
1 pc	Rear boot lid emblem " Logo "			na	\$55.10	✓
1 pc	Rear boot lid emblem " Vios "			na	\$53.20	✓
1 pc	Rear boot lid emblem " E "			na	\$35.10	✓
1 pc	Rear boot rubber			nd/cm	\$175.10	✓
2 pcs	Rear tail-lamp assy	photo C 422-50	\$485.10	CM	\$970.20	✓
2 pcs	Rear tail-lamp lower bracket		\$38.10	1m	\$76.20	X
2 pcs	Rear tail-lamp panel	? photo ok	\$205.10	1m	\$410.20	361.20
1 pc	Rear end panel			R1	\$605.10	✓
1 pc	Rear end panel inner garnish			Q17	\$237.40	✓
1 pc	Rear bumper	490		R1	\$587.60	✓
1 pc	Rear bumper reinforcement	288		R1	\$405.60	✓
2 pcs	Rear bumper side retainer	ok	ol/SD's	\$75.20	\$150.40	44.20
2 pcs	Rear bumper bracket	photo	BT10'i	\$95.20	\$190.40	✓
2 pcs	Rear bumper reflector	photo @ 112.00		\$155.60	CM	\$311.20
2 pcs	Rear reverse sensor	photo C 288-10	od/shon	\$385.70	\$771.40	✓
1 pc	Rear exhaust silencer			R	\$620.10	X
1 pc	Spare tyre panel	photo		BT1/Bu	\$698.60	✓
1 pc	Rear spare tyre cover board			CM	\$226.70	✓
2 pcs	Rear boot floor panel side sponge	photo	Defom	\$125.60	\$251.20	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Less 25 % \$2,553.65
balance c/f \$7,660.95

X 4446 R

S Nett

balance b/f \$7,660.95

1 pc Rear spare tyre panel black insulator
20 pcs Clip

mc \$200.00 *120rn*
\$2.00 *mc* \$40.00
\$240.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

1000 \$1,400.00

To putty & spray paint on rear accident affected portion.

900 \$1,400.00

Check/reconnect wiring.

20 \$40.00

To spray anti rust on accident affected portion.

60 \$120.00

Remove/refit rear boot upholstery to facilitate repair

80 \$150.00

Remove/refit rear windscreen to facilitate repair

mc x \$100.00 X

Remove/refit roof lining to facilitate replacement of rear o/s fender

mc \$150.00 X

Remove/renew rear exhaust silencer

mc x \$120.00 X
Total \$11,380.95