

VEHICLE REGN NO :

YP 384 L

OUR REFERENCE :

PAS/WM/210517/TP

**APPRAISEMENT SCHEDULE**

INSPECTION REPORT DATE : 17-May-21

CONTINUATION SHEET NO : 1

| S/No                                     | Qty | Parts / Labour Descriptions                  | Remarks / Condition | Repairer's<br>Estimate Amount<br>\$ cts | Recommendation /<br>Revised Amount<br>\$ cts |
|------------------------------------------|-----|----------------------------------------------|---------------------|-----------------------------------------|----------------------------------------------|
| <u>PARTS SUPPLY - SPECIAL NETT ITEMS</u> |     |                                              |                     |                                         |                                              |
| 1                                        | 1pc | N/s Centre Aluminium Door                    | Badly Dented        | 3000.00                                 | <del>3000.00</del><br>1500                   |
| 2                                        | 1pc | N/s Centre Aluminium Door lock               | Dislodged           | 220.00                                  | <del>220.00</del><br>150                     |
| 3                                        | 1pc | N/s Centre Aluminium Door logo and lettering | Necessary           | 600.00                                  | <del>600.00</del><br>300                     |
|                                          |     |                                              |                     | 3820.00                                 | <del>3820.00</del><br>1950                   |
| <u>LABOUR &amp; MISC. CHARGES</u>        |     |                                              | 1950                |                                         |                                              |
|                                          |     |                                              | 700                 |                                         |                                              |
|                                          |     |                                              | 2650                |                                         |                                              |
| 1                                        |     | Remove the necessary affected parts,         | <u>3 days</u>       |                                         |                                              |
|                                          |     | straighten n/s centre aluminium door         |                     |                                         |                                              |
|                                          |     | lower frame and rail and replace parts       |                     | 800.00                                  | <del>680.00</del><br>300                     |
| 2                                        |     | Remove and refit n/s centre door parts       |                     | 300.00                                  | <del>250.00</del><br>100                     |
| 3                                        |     | Spraypaint on all affected parts             |                     | 1000.00                                 | <del>800.00</del><br>300                     |
|                                          |     |                                              |                     |                                         | 700                                          |
| SUB / GRAND TOTAL                        |     |                                              |                     | 5920.00                                 | 5550.00                                      |

PRECISION APPRAISAL SERVICES

