

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R
8 Kaki Bukit Avenue 4
#08-09 Premier @ Kaki Bukit
Singapore 415875
Tel: 6341 6789 Fax: 6341 6778
Email: ishareauto@gmail.com



DATE : 09.06.21

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SCX3457J**
MODEL : **MIT-LANCER**
DATE OF ACCIDENT : 08.06.21
TIME OF ACCIDENT : 17:30HRS

JmYSNCKIAXu014167

Xiao chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 1,428.00	\$ 1,428.00
2	REAR BUMPER BEAM BRACKET <i>Best</i>	2	\$ 135.00	\$ 270.00
3	REAR BUMPER BEAM <i>Best</i>	1	\$ 296.00	\$ 296.00
4	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 58.00	\$ 116.00
5	REAR NUMBER PLATE LAMP <i>New</i>	2	\$ 59.00	\$ 118.00
6	TAIL LAMP <i>Cracked</i>	2	\$ 598.00	\$ 1,196.00
7	TAIL LAMP LOWER PANEL <i>LH Dented</i>	2	\$ 196.00	\$ 392.00
8	TAIL LAMP PANEL <i>Repair</i>	2	\$ 289.00	\$ 578.00
9	REAR FENDER INNER COWLING <i>Not New</i>	2	\$ 176.00	\$ 352.00
10	BOOT LID <i>Dented</i>	1	\$ 945.00	\$ 945.00
11	BOOT LID LAMP <i>Cracked</i>	2	\$ 260.00	\$ 520.00
12	BOOT LID LOGO	1	\$ 55.00	\$ 55.00
13	BOOT LID EMBLEM 'LANCER' <i>New</i>	1	\$ 69.00	\$ 69.00
14	BOOT LID EMBLEM 'MITSUBSHI'	1	\$ 65.00	\$ 65.00
15	BOOT LID EMBLEM 'GLXI'	1	\$ 62.00	\$ 62.00
16	BOOT LID HINGE <i>New</i>	2	\$ 125.00	\$ 250.00
17	BOOT LID TOP LOCK <i>Damaged</i>	1	\$ 189.00	\$ 189.00
18	BOOT LID LOWER LOCK <i>New</i>	1	\$ 21.00	\$ 21.00
19	BOOT LID WEATHER STRIP <i>Kit</i>	1	\$ 160.00	\$ 160.00
20	REAR END PANEL <i>Distorted</i>	1	\$ 629.00	\$ 629.00
21	REAR END PANEL TOP GARNISH <i>Dehnd</i>	1	\$ 144.00	\$ 144.00
22	REAR END PANEL INNER TRIM <i>Dehnd</i>	1	\$ 285.00	\$ 285.00
23	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 1,460.00	\$ 1,460.00
24	REAR FLOOR PANEL TOP BOARD <i>toen</i>	1	\$ 189.00	\$ 189.00
25	REAR FLOOR TOWING HOOK PANEL <i>Repair</i>	1	\$ 450.00	\$ 450.00
26	REAR CHASSIS MEMBER LH <i>Repair</i>	1	\$ 924.00	\$ 924.00
27	CENTER EXHAUST <i>New</i>	1	\$ 1,260.00	\$ 1,260.00

850

760

196

810

955

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SCX3457J**
 MODEL : **MIT-LANCER**
 DATE OF ACCIDENT : 08.06.21
 TIME OF ACCIDENT : 17:30HRS

28	CENTER EXHAUST INSULATOR <i>new</i>	1	\$ 195.00	\$ 195.00	X
29	CENTER EXHAUST GASKET (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
30	REAR EXHAUST PIPE <i>Best</i>	1	\$ 959.00	\$ 959.00	685
31	REAR EXHAUST MOUNTING <i>part</i>	2	\$ 56.00	\$ 112.00	+
32	REAR EXHAUST INSULATOR <i>new</i>	1	\$ 185.00	\$ 185.00	+
33	REAR EXHAUST GASKET <i>new</i>	1	\$ 60.00	\$ 60.00	30-

7335
660.50

TOTAL PRICE \$ 13,994.00
 LESS 10% \$ 1,399.40
SUB TOTAL PRICE \$ 12,594.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00	X
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30-
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20-
4	TAIL LAMP LOWER PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
7	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10-
10	REAR END PANEL INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	20-
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60-
12	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	60-
13	REAR FLOOR TOWING HOOK PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
14	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>ht</i>	1	\$ 350.00	\$ 350.00	100-
15	REVERSE SENSOR <i>Band</i>	1	\$ 220.00	\$ 220.00	20-

500

\$ 1,700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, GRAZE, KNOCK STRAIGHTEN, ADJUST AFFECTED PARTS	\$ 1,800.00	1200
2	TO PUTTY, SPRAY PAINT POLISH, WAX	\$ 1,800.00	1000
3	TO SPRAY TUFF COAT	\$ 250.00	80-
4	WIRING, BULB CHECKING	\$ 120.00	30
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	80-

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SCX3457J**
MODEL : **MIT-LANCER**
DATE OF ACCIDENT : 08.06.21
TIME OF ACCIDENT : 17:30HRS

6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,920.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,294.60
TOTAL LABOUR COST : \$ 4,920.00
TOTAL REPAIR COST : \$ 19,214.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
MICHELLE
HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
2/5 10/06/21.
09 Days

total 9681.50

2/5: 7.7K ✓

2580