



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP Grab

Ashes

SALVA2AG7HH263392

Page No. 1

Vehicle No. SLV1070H RANGE ROVER

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>Detoured</i>		2350.00	/
1	FRONT BUMPER SIDE BRACKET LH <i>Dm d</i>		135.00	/
1	FRONT BUMPER LOWER BRACKET LH <i>crushed</i>		215.00	/
1	FRONT BUMPER LOWER LAMP LH <i>crushed</i>		425.00	/
1	FRONT BUMPER LOWER LAMP GARNISH LH <i>crushed</i>		342	/
1	FRONT BUMPER LOWER LAMP CHROME LH <i>ut</i>		282	/
1	FRONT BUMPER REINFORCEMENT <i>He new</i>		855.00	X
1	FRONT BUMPER Reinforcement Cover. <i>crushed</i>		225.00	✓
1	FRONT BONNET <i>He new</i>		1999.27	X
2	FRONT BONNET HINGE LH & RH @\$185.60 <i>He new</i>		371.20	X
1	FRONT BONNET EMBLEM <i>He new</i>		81.00	X
1	FRONT HEADLAMP LH <i>crushed</i>		3943	✓
1	FRONT HEADLAMP CONTRL UNIT LH <i>He new</i>		510	X
1	FRONT SUPPORT PANEL <i>He new</i>		740.10	X
1	FRONT FENDER LH <i>He new</i>		925.60	X
1	FRONT FENDER EMBLEM <i>He new</i>		81.00	X
1	FRONT Fender Arc Garnish <i>ut</i>		211.00	✓
	Radiator <i>1660</i>			
	<i>crushed</i> <i>930</i>			
		less	10%	10%
			8614.17	
			861.42	
			7752.76	
	SPECIAL ITEMS			
1 SET	FRONT BUMPER CLIPS <i>new</i>		80.00	30
1 SET	FRONT FENDER CLIPS <i>new</i>		100.00	30
1 SET	FRONT CAR PLATE WITH COVER <i>new</i>		70.00	X
	Total Parts		8002.76	

1 Bot Coolant.

~~100.~~ 60.

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLV1070H RANGE ROVER

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	500.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	250
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	x
5	To remove and replace front headlamp beam	80.00	x
6	To clear fault code with diagnostic computer and reset to Range Rover specification.	250.00	180
7	To remove radiator	120	100.
Labour Total :		4060.00	1060
TOTAL (PARTS & LABOUR):		12062.76	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin

H/S 04 Days

Total: 9386.20

H/S: 7.5k

(7.514)