

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal notification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Automotive Services

Estimation

Acknowledged by Repairer

Signature:

Date:

LIMIT \$3,500

AP AUTOMOTIVE SERVICES PTE LTD
ROC: 202022890H
BLOCK 8006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Date

Vehicle

Make/Model

Chassis No.

SGP 2714 T

MAZDA 3

JM6BK106270320501

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BOOTLID / DD	1		\$ 258.00
2	BOOTLID LOGO - MAZDA / NEC	1	\$ 79.50	\$ 79.50
3	BOOTLID EMBLEM - MAZDA 3 / NEC	1	\$ 58.70	\$ 58.70
4	BOOTLID LAMP L+R XSVL / CRK	2	249.50	\$ 499.00
5	BOOTLID LOCK CYLINDER ? XSVL	1		\$ 446.00
6	BOOTLID LOCK / DEF	1	\$ 291.80	\$ 291.80
7	BOOTLID LOCK CATCH / DEF	1	\$ 74.00	\$ 74.00
8	BOOTLID INNER TRIM ? / TN	1	\$ 147.70	\$ 147.70
9	BOOTLID HINGE SET ? XSVL	2	\$ 81.35	\$ 162.70
10	BOOTLID STOPPER SET XSVL	2	\$ 22.25	\$ 44.50
11	BOOTLID WEATHERSTRIP ? / DEF	1		\$ 131.00
12	TAIL LAMP L+R XSVL / CRK	2	408.00	\$ 816.00
13	TAIL LAMP PANEL L+R XSVL	2	439.00	\$ 878.00
14	REAR BUMPER / CRK	1		\$ 976.00
15	REAR BUMPER NUMBER PLATE LAMP L+R / CRK not working	2	\$ 65.90	\$ 131.80
16	REAR BUMPER REFLECTOR L+R XSVL / CRK	2	\$ 67.50	\$ 135.00
17	REAR BUMPER RETAINER L+R ? L - CRK	2	\$ 78.80	\$ 157.60
18	REAR BUMPER REINFORCEMENT BAR ? XSVL	1		\$ 476.00
19	REAR BUMPER SPONGE ?	1	\$ 137.80	\$ 137.80
20	REAR BUMPER UNDERCOVER ? XSVL	1	\$ 293.65	\$ 293.65
21	REAR WINDSCREEN MOULDING / NEC	1		\$ 39.00
22	REAR FENDER L+R XSVL	2	1781.00	\$ 3562.00
23	REAR FENDER INNER TRIM L+R XSVL	2	\$ 271.55	\$ 543.10
24	REAR FENDER COWLING L+R ? XSVL	2	\$ 152.90	\$ 305.80
25	END PANEL X R	1		\$ 459.00
26	END PANEL TOP GARNISH ? - CRK	1	\$ 219.80	\$ 219.80
27	REAR SMART LOCK ANTENNA ? XSVL	1	\$ 197.30	\$ 197.30
28	SPAREWHEEL PANEL ? X R	1		\$ 976.00
29	SPAREWHEEL PANEL TOP BOARD ? XSVL	1		\$ 411.00
30	SPAREWHEEL PANEL ACCESSORIES SPONGE ? XSVL	1	\$ 102.70	\$ 102.70
31	EXHAUST PIPE X R	1		\$ 831.00
32	EXHAUST MOUNTING ? XSVL	1		\$ 45.00
33	EXHAUST HEAT SHIELD ? XSVL	1		\$ 126.00
	Total		\$ 16,050.45	3,083.45
	Less 20%		\$	616.69
	Total		\$ 12,040.36	2,466.76

S/Nett Items					
1	BOOTLID SPOILER X SU	1	800	\$	800.00
2	BOOTLID SPOILER SEALANT X NN	1	100	\$	100.00
3	BOOTLID INNER TRIM CLIPS ? / NEL	1	100	\$	30 100.00
4	BOOTLID EMBLEM BATMAN	1	300	\$	300.00
5	REAR NUMBER PLATE / CRK	1	100	\$	100.00
6	TAIL LAMP CLIPS ? / NEL	1	50	\$	30 50.00
7	TAIL LAMP PANEL SEALANT ? X NN	1	120	\$	120.00
8	REAR BUMPER CLIPS / NEL	1	100	\$	50 100.00
9	REAR BUMPER REVERSE SENSOR SET XXX / not working	1	300	\$	200 300.00
10	REAR BUMPER LOWER DIFFUSOR SET X SU	1	1600	\$	1,600.00
11	REAR WINDSCREEN SEALANT / NEL	1	120	\$	120.00
12	REAR FENDER SEALANT ? X NN	1	200	\$	200.00
13	REAR FENDER INNER TRIM CLIPS ? X NN	2	100	\$	200.00
14	REAR FENDER COWLING CLIPS ? X NN	2	100	\$	200.00
15	END PANEL SEALANT X NN	1	200	\$	200.00
16	END PANEL TOP GARNISH CLIPS ? / NEL	1	100	\$	30 100.00
17	SPAREWHEEL SEALANT ? X NN	1	250	\$	250.00
			Total	\$	4540.00 4,590.00

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS 400	1	2400	\$	600 2,400.00
2	SPRAY PAINT ON AFFECTED AREAS 400	1	1800	\$	600 1,800.00
3	TO RNR REAR WINDSCREEN 120	1	400	\$	120 400.00
4	TO RNR REAR EXHAUST ? / NEL	1	350	\$	50 350.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION ? / NEL	1	150	\$	150.00
6	TO CHECK WIRING AND BOOTLID LAMP FUNCTION ? / NEL	1	150	\$	150.00
7	TO RNR REAR INNER TRIM AND UPHOISTERY ? X NN	1	400	\$	400.00
8	TO CHECK WATER LEAK X NN	1	150	\$	150.00
9	TO RNR FUEL TANK ? X NN	1	250	\$	250.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS ? X NN	1	600	\$	600.00
11	TO RNR REAR BOOT MECHANISM ? / NEL	1	350	\$	50 350.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION 30	1	150	\$	30 150.00
13	TO PERFORM RUST PROOFING	1	300	\$	80 300.00
			Total Labour	\$	7,450.00
			Parts Replacement Amount	\$	7,056.76
			Total Amount	\$	14,506.76

NAZ UKK

9/6/2021 1700

LIS

4 DAYS

CHECK ITEM PHOTO

- AFTER REPAIR PHOTO

- need to check repair limit and MV as COE exp 30/11/2021.

- Repairer agreed to Lump Sum Repair \$3,000.00 / 4 REPAIR DAYS