

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: **SJU5142L**  
 Model and make: **Hyundai Avante**  
 Chassis number: **KMHDU41BMAU896649**

**Qty Spare parts**

List price **2009**

1	Front bumper	S	✓	442.80	BR ✓
1	Front bumper LH side retainer	S	✓	32.00	NEC ✓
1	Front bumper inner sponge	S	✓	114.00	BR ✓
1	Front bumper reinforcement	S		<del>254.50</del>	NDX
1	Front bumper lower cover	S		<del>123.00</del>	NDX
1	Front LH fender	S	✓	437.30	DD ✓
1	Front LH fender splash shield	S	✓	67.30	BR ✓
1	Front LH fender "VVT" emblem	S	✓	41.60	NEC ✓
1	LH headlamp assy	S		450.00	513.10
1	LH headlamp lower bracket	S			42.00
1	Support panel	S		457.00	812.70
1	Front grille (lower)	S		178.00	389.40
1	Front grille emblem	S			<del>38.90</del>
1	Front LH sport rim	S			458.20
1	Front LH lower arm	S			<del>538.00</del>
1	Front LH knuckle arm	S			<del>640.80</del>
1	Front LH wheel bearing	S			<del>224.60</del>
1	Front LH wheel hub	S			<del>391.40</del>
1	Front LH shock absorber	S			<del>385.10</del>
1	Front LH drive shaft	S			841.30

		S		6,788.00
@ 20%	2,220.00	S		1,357.60
	444.00	S	-20%	5,430.40
	<u>1,776.00</u>			

**Qty Spare parts**

Special Nett price

1set	Front bumper clips	S	30.00	80.00	NEC ✓
1set	Front LH fender splash shield clips	S	30.00	80.00	NEC ✓
1	Radiator coolant	S		<del>50.00</del>	NNX
1	Front LH tyre	S		280.00	} NNX
1	Brake fluid	S		<del>50.00</del>	
				60.00	

**Labour and painting**

Labour charges to remove, check, replace and reinstall damages bodyparts. S 600.00 900.00 ✓  
 To panel beating, cut / weld and re-align all affected panels

Spray painting on affected panels	\$ 400.00	<del>900.00</del> ✓
Check wiring and lighting system	\$	<del>80.00</del> N/A
Apply rust coating on affected areas	\$	<del>60.00</del> N/A
Remove and reinstall aircon condenser, pipes and hoses to assist repairs. To refill aircon gas	\$	<del>180.00</del> }
Remove and reinstall radiator, hoses and fan assy to assist repairs. To refill coolant	\$	<del>180.00</del> } N/A
Refocus and adjust headlamps assy	\$	<del>50.00</del> }
Remove, reinstall and replace front LH undercarriage parts	\$	<del>280.00</del> }
Conduct and adjust wheel alignment system	\$	<del>100.00</del> }

Survey and Resurvey  
 On 10/5/2021  
 12 Hours  
 TGLim Lim

Total: \$ 8,700.40

1,000.00

Lump sum repair  
 Repair days 5

Parts	1776.00
SN	60.00
Labour	1,000.00
	<hr/>
	2,836.00
@ 20%	567.20
	<hr/>
	2,268.80

L/S 2,250/2

TGLim Lim  
 10/6/2021

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: