

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 23 Jun 2021

Preliminary Advice

Insured Vehicle No : GBG5885U
TP Vehicle No : SJU5142L Accident Date : 08/06/2021
Make : HYUNDAI AVANTE Assignment Date : 09/06/2021
Date of Inspection : 10/06/2021 Est. Duration of Repair : 5
Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)
8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT
SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,700.40
Revised Amount	:S\$	2,836.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,836.00
Lump Sum Repair	:S\$	2,250.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :