

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006551/R1PA3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800112625
Claimant Vehicle No :	SG7005D	Insured Vehicle No :	SME3594C
Date of Loss:	03/06/2021	Nature of Claim:	TP
		Claim No:	9164165061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG7005D	Engine No:	HIDDEN
Make & Model:	YUTONG ZK6125BEVGS, 6.7 E (A)	Chassis No:	LZYTAGEWXL1056949
Reg. Date:	04/06/2020 (Man. Year: 2020)	Odometer:	29428 km
Colour:	Green		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	305/70 R22.5	Rear Tyre Size:	305/70 R22.5 (D)
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8/8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,930.00	200.00	1,730.00	89.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,060.00	2,320.00	68.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,310.00	1,260.00	4,050.00	76.27
+ GST 7.00/7.00% (S\$)	371.70	88.20	283.50	76.27

Nett Amount (S\$)	5,681.70	1,348.20	4,333.50	76.27
		<hr/>		
+ Loss of Use (3.0 x S\$300.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
		<hr/>		
Nett Liability (S\$)		2,250.20		
		<hr/>		
Global Sum Settlement (S\$)		2,250.00		
		<hr/>		

INSPECTION

Date of Assignment: 09/06/2021

Date Inspected: 10/06/2021

Estimated Period of Repair: 3.0 days

Inspected At: Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*OS BATTERY COMPARTMENT DOOR MTG	Repair	840.00 F	*- F
2	1		*OS REAR LAST COMPARTMENT	Repair	840.00 F	*- F
3	1		*ADVERTISEMENT STICKER	Necessary	250.00 F	*200.00 F
F=Franchise part.						
Total Parts (S\$)					1,930.00	200.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE :OS BATTERY COMPARTMENT DOOR MTG ,OS REAR LAST COMPARTMENT DOOR MTG	New	1,950.00	320.00
2	SPRAY PAINTING:OS BATTERY COMPARTMENT DOOR MTG ,OS REAR LAST COMPARTMENT DOOR MTG	New	1,280.00	640.00
3	CONTRACTORS COST: TO REPLACE ADVERTISEMENT STICKER	New	150.00	100.00
Gross Labour Cost (\$\$)			3,380.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >