

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21006552/UPA3Q2
Date: 20/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070164719
Claimant Vehicle No :	SKT5315Z	Insured Vehicle No :	SMW5391M
Date of Loss:	08/06/2021	Nature of Claim:	TP
		Claim No:	7268110788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT5315Z	Engine No:	2ZR1517308
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE206020340
Reg. Date:	12/06/2015 (Man. Year: 2015)	Odometer:	112484 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,070.32	1,785.42	3,284.90	64.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,135.00	1,610.00	525.00	24.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,205.32	3,395.42	3,809.90	52.88
Approved Total (Overridden) (S\$)		2,700.00		

(S\$)	7,205.32	2,700.00	4,505.32	62.53
+ GST 7.00/7.00% (S\$)	504.37	189.00	315.37	62.53
Nett Amount (S\$)	7,709.69	2,889.00	4,820.69	62.53
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,211.00		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 09/06/2021

Date Inspected: 09/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

NPH Auto Service (HQ)
 Blk 9005 Tampines Steet 93, #01-246/254
 Singapore 528839

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	584.70 FL	*- FL	
2	1		*FRONT FENDER RH	Badly Dented	851.20 FL	*851.20 FL	
3	1		*FRONT FENDER INNER COWLING	Distorted	172.70 FL	*172.70 FL	
4	8		*FRONT FENDER INNER COWLING CLIPS	Necessary	40.00 FL	*40.00 FL	
5	1		*FRONT DOOR RH	Repair	1,395.00 FL	*- FL	
6	1		*FRONT DOOR BLACK STICKER	Not Necessary	45.00 FL	*- FL	
7	1		*FRONT DOOR BLACK STICKER (INNER)	Not Necessary	40.00 FL	*- FL	
8	1		*FRONT DOOR W/STRIP RUBBER	Not Necessary	175.00 FL	*- FL	
9	1		*FRONT DOOR HINGE TOP	Serviceable	85.00 FL	*- FL	
10	1		*FRONT DOOR HINGE BOTTOM	Serviceable	80.00 FL	*- FL	
11	1		*FRONT DOOR SIDE MIRROR ASSY RH	Repair	988.50 FL	*- FL	
12	1		*RUNNING BOARD SPOILER	Torn	1,090.00 FL	*1,090.00 FL	
13	1		*FRONT FENDER CARBON FIBRE STICKER	Necessary	280.00 FS	*120.00 FS	
14	1		*FRONT DOOR SUPPORT RUBBER	Distorted	50.00 FS	*50.00 FS	
15	1		*FRONT SPORT RIM	Repair	580.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	6,457.10	2,323.90
					- List Item Discount on L Items 25.00/25.00% (\$)	1,386.78	538.48
					Total Parts (\$)	5,070.32	1,785.42

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RESET WHEEL CAMBER ALIGNMENT	New	100.00	60.00
2	REMOVE & INSTALL F/BUMPER ,F/FENDER ,F/DOOR ,RUNNING BOARD SPOILER ,KNOCK DOOR PILLAR RUNNING BOARD PANEL AND RESTRAIGHEN BODY	New	800.00	550.00
3	SPRAY PAINTING	New	1,200.00	980.00
4	CHECK WIRING SYSTEM	New	35.00	20.00
Gross Labour Cost (\$\$)			2,135.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >