



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :

Page : 1/2

Our Ref : TP0047/06/21

Date : 09/06/2021

THIRD PARTY CLAIM

M/S : TEO CHEE KOON
BLK 17A CIRCUIT ROAD
#07-200
SINGAPORE 371017

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SKT5315Z - TOYOTA WISH
INSURED : TEO CHEE KOON
DATE OF ACCIDENT : 08/06/2021
POLICY NO : MP313129

ENGINE# :

CHASSIS# :

*not Allowed
9/6/21
4/5 \$3800
4 days
Chybl the up*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
Replacement of Parts				
1 front bumper <i>R</i>	1@	584.70	584.70	584.70 X
2 front fender RH <i>Body</i>	1@	851.20	851.20	851.20 ✓
3 front fender inner cowling <i>Dis</i>	1@	172.70	172.70	172.70 ✓
4 front fender inner cowling clip <i>per</i>	8@	5.00	5.00	40.00 ✓
5 front door RH <i>Best/wrap</i>	1@	1395.00	1395.00	1,395.00 ✓
6 front door black sticker <i>ner</i>	1@	45.00	45.00	45.00 ✓
7 front door black sticker <i>ner</i>	1@	40.00	40.00	40.00 ✓
8 front door w/strip rubber <i>ner</i>	1@	175.00	175.00	175.00 ✓
9 front door hinge top <i>Best</i>	1@	85.00	85.00	85.00 ✓
10 front door hinge bottom <i>Best</i>	1@	80.00	80.00	80.00 ✓
11 front door side mirror assy RH <i>R</i>	1@	988.50	988.50	988.50 X
12 running board spoiler <i>Don</i>	1@	1090.00	1090.00	1,090.00 ✓
				5,547.10
				-1,386.78
				\$4,160.32
Special Nett Items				
13 front fender carbon fibre sticker <i>ner</i>	1@	280.00	280.00	280.00 120
14 front door support rubber <i>Dis</i>	1@	50.00	50.00	50.00 ✓
15 front sport rim <i>R</i>	1@	580.00	580.00	580.00 X
				910.00

Less 25%

Total Material

Special Nett Items

Total S/Nett

Labour & Misc

1 Reset wheel camber alignment.

\$910.00

100.00 60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg



Registration No.: QAIC / SG / 106

Your Ref :

Page : 2/2

Our Ref : TP0047/06/21

Date : 09/06/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
2 Remove & install f/bumper, f/fender, f/door, running board spoiler, knock door pillar, running board panel and restraighen body.				800.00
3 Spray painting.				1,200.00
4 Check wiring system.				35.00
				2,135.00

Total Labour

\$2,135.00

Nett Total Before Gst

\$7,205.32

Your faithfully

NPH AUTO SERVICE
(Manager)

1-3983.90
2980.42