



Section A - Accident Details

Registration Number	SHB1051R
Case Reference Number	TAX/06/21/2011
Registration Date	17/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SHAHLAN BIN SHAMSURI
Type of Accident	Side Swipe
Accident Date and Time	5/6/2021 8:48 PM
Accident Reported Date and Time	7/6/2021 9:47 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111191
Special Instruction to ARC, if any	LEFT FRONT PORTION
Prepared Date and Time	7/6/2021 12:52 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$1,494.00	\$800.00
Total Spare Part Cost	\$5,470.25	\$879.00
Total Other Cost	\$725.00	\$170.00
TOTAL COST	\$8,196.25	\$2,149.00 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Taufikh (LKK) / AIG
ARC / Surveyor Sign Off Date	07/06/2021 1:02 PM	08/06/2021 2:54 PM
Signature		
Remarks		RESURVEY BEFORE PAINT P/P

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2106-0298	Invoice Number	
Quotation Date	17.06.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$507.00	\$300.00
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$100.00
RESPRAY MIRROR COVER LH	\$180.00	\$100.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$725.00	\$170.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68216-47010	WEATHERSTRIP, FRONT DOOR FIX WINDOW , LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		68126-47010	GLASS, FRONT DOOR FIX WINDOW , LH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given
		60118-47020	COVER SUB-ASSY, FRONT PILLAR , UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Not Given
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,300.70	100.00	\$0.00	Replace	Repair
		87940-47440	MIRROR ASSY, OUTER REAR VIEW , LH	0.00	\$1,339.30	0.00	\$0.00	Replace	Not Given
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$108.60	100.00	\$0.00	Replace	Repair
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair
		53852-47041	PAD, FR WHEEL LH	1.00	\$59.60	25.00	\$44.70	Replace	Replace
		53876-47060	LINER, FR FENDER, LH	0.00	\$210.30	0.00	\$0.00	Replace	Not Given
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace

X nn
X nn
X nn
√ nec
R
X nn
R
X nn
R nn
√ nec
X nn
√ na

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/06/2021

User ID PohSuan

		53802-47100	FENDER SUB-ASSY, FR , LH	1.00	\$977.80	25.00	\$733.35	Replace	Replace
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	100.00	\$0.00	Replace	Repair
Total					\$6,963.54		\$879.00		

√ bt
X nn
R

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

879.00
+ 300.00
+ 970.00
2,149.00

Case Details

Case Reference Number : TAX/06/21/2011
Type of Repair : Accident Repair
Vehicle Registration Number : SHB1051R

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-15107-ID
Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 05/06/2021 12:48 PM
Vehicle Age(In Months) : 18

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	521.00	521.00	25.00	390.75	Replace	1	0	Repair	Rx
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	Xun
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	977.80	977.80	25.00	733.35	Replace	1	733.35	Replace	bt-
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	un-
One Time Key In	Main			LINER, FR FENDER, LH	1	210.30	210.30	25.00	157.73	Replace	0	0	Not Give	Xun
One Time Key In	Main			PAD, FR WHEEL LH	1	59.60	59.60	25.00	44.70	Replace	1	44.70	Replace	un-
One Time Key In	Main			WHEEL, DISC FRONT	1	1,879.40	1,879.40	25.00	1,409.55	Replace	1	0	Repair	Rp
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xun
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	108.60	108.60	25.00	81.45	Replace	1	0	Repair	Ry
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,339.30	1,339.30	10.00	1,205.37	Replace	0	0	Not Give	Xun

Total Spare Part Cost 5,470.25

Lump Sum Discount (%) 0.00

Final Spare Part Cost 5,470.25

Surveyor Total 879.00

Lump Sum Dis (%) 0

Final Sur Total 879.00

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,300.70	1,300.70	25.00	975.53	Replace	1	0	Repair	Ry
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	Ne
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR, UPR LH	1	96.90	96.90	25.00	72.68	Replace	0	0	Not Give	Xun
One Time Key In	Main			GLASS, FRONT DOOR FIX WINDOW, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xun
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	Xun

Total Spare Part Cost 5,470.25

Surveyor Total 879.00

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 5,470.25

Final Sur Total 879.00

879

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	300	
Total:			507.00	300.00 ✓	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	100	
4	Main	RESPRAY MIRROR COVER LH	180.00	100	
5	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
Total:			1,494.00	800.00 ✓	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			725.00	170.00	

U21

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	60	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			725.00	170.00 ✓	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,470.25	879.00
Total Labour Cost	507.00	300.00
Total Spray Painting	1,494.00	800.00
Other	725.00	170.00
Overall Total	8,196.25	2,149.00
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	8,200.00	2,149.00
Surveyor Approved Amount		2,149.00
No of Repair Days*	5	3
Remarks		RESURVEY BEFORE PAINT P/P

Surveyor Name

Signature

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: 08/06/2021
Date:

Taufikh

Save Clear

Taufikh 97415747
8/6/21
WP 3 days
P/P Resurvey before paint
taufikh@lkkauto.com

879
300
800
170

\$ 2149
3 days. #