

ASS. REC. BY:

REF:

C72 / 210065571KV f3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLX 55Z

Policy No. DMPCSNW00099342000


Claims No. SNM21D203272/C02/TANKW

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 7030 Yr Regn: 12, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle c.c. 1496

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: 5116 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 8 . 2101909

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 9/6/21 D.O.I. 10/6/2021

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S 151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/10/21 Kenneth confirmed \$5894 (Red 230, 3%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

12/10/21-typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Fuel

Others

Add Fee: : Site Insp (\$


: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format: Merimen

ump Sum / I.B.I.: (\$ 5894

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
NA

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (SLX55Z)
Policy No:		Date of Loss:	09/06/2021
Vehicle Reg. No.:	SMW7030S	Driveable?	
Party At Fault:	UNKNOWN		

Make/Model:	HONDA SHUTTLE, 1.5 G (A)	Vehicle Reg. Date:	02/12/2020
Vehicle Colour:	RED		
Engine No:	L15B6022249	Chassis No:	GK82101909
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

*Not authorized
Paying B4 pay
6 days*

Description of Accident/Loss: REFER TO STATEMENT

Remarks: VEHICLE TOW INTO ANG MO KIO WORKSHOP ON 10/06/2021.

Present Location: CHENG HOE MOTOR PTE LTD (AMK)

COST OF CLAIMS

	LKK Auto Consultants hence notify the Repairer of the following:	Amount
Parts	• To resurvey before/after spray painting	3,669.00
Miscellaneous Items	• To display damaged part(s) during resurvey	235.00
Labour	• Parts prices are subject to confirmation	2,220.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	0.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	0.00
	Gross Total (S\$)	6,124.00
	Acknowledged by Repairer	
	Signature: GST 7.00% (S\$)	428.68
	Date: Nett Amount (S\$)	6,552.68

his claim is handled by: DORLYN LI YAZHU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jun 2021)
Parts:	N/A HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW7030S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper	Bj 0.00	0.00	*540.00 F ✓
2	1		*1 pc front bumper reinforcement	Bj 0.00	0.00	*260.00 F ✓
3	1		*1 pc front bumper lower centre grille	D/I 0.00	0.00	*90.00 F ✓
4	1		*1 pc front bumper LH side fog lamp garnish	M/I 0.00	0.00	*60.00 F ✓
5	1		*2 pcs front bumper side retainers @ \$9/pc	CM 0.00	0.00	*18.00 F ✓
6	1		*6 pcs front bumper side retainers @ \$2/pc	CM 0.00	0.00	*12.00 F ✓
7	1		*1 pc front grille housing	Mj CM 0.00	0.00	*170.00 F ✓
8	1		*1 pc front grille housing outer garnish	CM 0.00	0.00	*250.00 F ✓
9	1		*1 pc front grille logo (black)	CM 0.00	0.00	*255.00 F ✓
10	1		*1 pc front grille lower chrome	CM 0.00	0.00	*100.00 F ✓
11	1		*2 pcs headlamps @ \$510/pc	0.00	0.00	*1,020.00 F ✓
12	1		*2 pcs headlamp lower brackets @ \$36/pc	CM 0.00	0.00	*72.00 F ✓
13	1		*1 pc front support panel	0.00	0.00	*390.00 F ✓
14	1		*1 pc front LH fender	Bj 0.00	0.00	*150.00 F ✓
15	1		*1 pc front LH fender inner shield	CM 0.00	0.00	*85.00 F ✓
16	1		*6 pcs front LH fender inner shield clips @ \$2/pc	CM 0.00	0.00	*12.00 F ✓
17	1		*1 pc front LH fender extension arm	Bj 0.00	0.00	*95.00 F ✓
18	1		*1 pc front LH fender gusset plate	D/I 0.00	0.00	*40.00 F ✓
19	1		*1 pc front LH fender gusset	Bj 0.00	0.00	*50.00 F ✓
Total Parts (\$\$)						3,669.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Io	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc front LH rim	200.00 ✓
1	1	1 unit coolant	35.00 ✓
Sub Total (\$\$)			235.00

Estimates on Labour

Particulars	Lab.Type	Amount
<u>Labour Items</u>		
Towing	New	50.00 ✓

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Particulars	Lab Type	Amount
Remove & refill air-con condenser, vacuum & refill gas	New	✓ 100.00
Remove & refill front bumper & attachments, grille, front LH fender, to cut weld & renew fit LH fender extension, arm, fit support panel; knocking & repair front LH chassis frame & realign the same	New	841 900.00
Putty & respray front bumper, bonnet, both fenders, fit support panel, fit LH door & all affected areas	New	514 1,000.00
Remove & refill fit LH rim, tyre, balance & realign the same	New	201 50.00
To conduct computer wheel alignment	New	✓ 60.00
Rustproofing	New	✓ 60.00
Gross Labour Cost (\$)		2,220.00

Report was unsubmitted during this print-out.
Generated using Marimon e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/06/2021 13:44 (SGT)
Date of Accident 09/06/2021 09:46 (SGT)
Exact Location of Accident Singapore
Additional Location Information OUTSIDE NO.14 SELETAR GREEN VIEW
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMW7030S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner CHAN YING JIAN
NRIC No SXXXX714B
Email Address yingjian.chan@gmail.com
Mobile Phone No (Phone) +65-97711032
Alternative Phone No +65-97711032

VEHICLE PARTICULARS

Manufacturer Honda
Model Shuttle
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500


INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5119979220 DC
Cover Note Number 02/12/2020 - 01/12/2021

DRIVER

Name of Driver CHAN YING JIAN
NRIC No SXXXX714B

Sketch Plan



A: SMW 7030S
(alone)

B: SLX 55Z
Porsche
lady driver (alone)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SMW 7030S (NTUC)

Date & Time: 09/06/2021 @ 0946 (clear day)

I was driving along Selekar Green View towards the main road. Out of a sudden, felt an impact on my car front LH portion. Motor car SLX 55Z had drove out of her house without checking and collided onto my bypass vehicle front LH portion. Upon alighting, driver of SLX 55Z merely told me to leave it the legal way, called out her hubby to talk to me and drove another family car out. As her hubby has refused to provide any other information on driver of SLX 55Z, i took some scene photos and called for towing services to the nearest Authorised workshop. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop