



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 070120

Contact : -

Fax No. : 6880 4838

Not Notarized
Clay &
Murray After Rain
18 days

Estimate : QUOT202106-000279(00)

Date : 09/06/2021

Vehicle No. : SLQ2896L

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Mileage (km) : 0

Chassis No. : MMBSTA13AHH006392

Accident Date : 06/06/2021 00:00:00

Claim No. : SLT6973E

Reference : JO202106-0402

Policy No. : 5101728531-02

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS :				
1	Rear bumper	1.0	708.00	mi 708.00 ✓
2	Rear bumper retainer	2.0	22.00	cm 44.00 ✓
3	Rear Bumper clips	10.0	5.00	na 50.00 ✓
4	Rear bumper shield	2.0	38.00	ol/mi 76.00 ✓
5	Rear bumper reflector	2.0	20.00	mi 40.00 ✓
6	Rear RH fender	1.0	715.00	R 715.00 ✓
7	Rear RH fender inner trim	1.0	158.00	Reform 158.00 ✓
8	RH taillamp	1.0	276.00	Br 276.00 ✓
9	RH taillamp panel	1.0	89.00	R 89.00 ✓
10	RH taillamp clip holder	1.0	5.00	na 5.00 ✓
11	Rear end panel	1.0	402.00	R 402.00 ✓
12	Rear end panel top garnish	1.0	64.00	Sn 64.00 X
13	Rear floor panel	1.0	906.00	R 906.00 ✓
14	Rear exhaust muffler	1.0	571.00	571.00 ?
15	Rear RH rim	1.0	710.00	Per 710.00 X
16	Rear RH wheel bearing	1.0	114.00	na 114.00 X
17	Rear RH shock absorber	1.0	204.00	Sh 204.00 X
18	Rear axle beam	1.0	959.00	Sn 959.00 X
19	Rear RH door lock	1.0	290.00	R 290.00 X
20	Front bumper	1.0	666.00	R 666.00 ✓
21	Front bumper tow cover	1.0	36.00	na 36.00 ✓
22	Front bumper lower grille	1.0	156.00	Di 156.00 ✓
23	Front bumper clip	10.0	5.00	na 50.00 ✓
24	Front bumper tow cover	1.0	36.00	Ag 36.00 X
25	Front bumper retainer	2.0	22.00	44.00 ?
26	Front bumper reinforcement	1.0	139.00	R 139.00 ✓
27	Front grille	1.0	525.00	525.00 ?
28	Front grille logo	1.0	42.00	42.00 ?
29	Rh Fog Lamp	1.0	274.00	274.00 ?
30	Rh Fol Lamp cover	1.0	120.00	Sn 120.00 X
31	Headlamp	2.0	544.00	ol/m/cm 1,088.00 ✓
32	Front support panel	1.0	1,058.00	R 1,058.00 X
33	Air con condenser	1.0	683.00	Sn 683.00 X
34	Air con discharge pipe	1.0	190.00	Sn 190.00 X
35	Air con liquid pipe	1.0	275.00	Sn 275.00 X

CONTINUE NEXT PAGE

Page 1 of 3



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

Estimate : QUOT202106-000279(00)

Date : 09/06/2021

Vehicle No. : SLQ2896L

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Mileage (km) : 0

Chassis No. : MMBSTA13AHH006392

Accident Date : 06/06/2021 00:00:00

Claim No. : SLT6973E

Reference : JO202106-0402

Policy No. : 5101728531-02

S/No	Particular	Quantity	Unit Price	Amount S\$
36	Radiator	1.0	872.00	872.00 X
37	Fan cowling	1.0	117.00	117.00 X
38	Fan motor	1.0	374.00	374.00 X
39	Fan blade	1.0	70.00	70.00 X
40	Radiator upper air guide	1.0	106.00	106.00 CM
41	Radiator lower air guide - LH	1.0	18.00	18.00 CM
42	Radiator lower air guide - RH	1.0	18.00	18.00 X
43	Rear keyless entry buzzer	1.0	92.00	92.00 X
List Total :				13,430.00
10% Discount S\$				1,343.00
				12,087.00
SPECIAL NET :				
1	Reverse sensor	1.0	250.00	250.00 Mr's 2000
2	Rear windscreen glass sealant	1.0	40.00	40.00 Mr's
3	Insulator paste	1.0	40.00	40.00 Mr's
4	Off - peak vehicle license plate seal	1.0	20.00	20.00 Mr's
SPECIAL NET Total S\$:				350.00
LABOUR :				
-	To remove and refit rear trims, seats and upholstery	1.0	120.00	120.00 1000
*	To remove and refit rear windscreen glass	1.0	150.00	150.00 1200
-	To supply panel sealant and to seal off all weld spot seams and gaps	1.0	90.00	90.00
-	To spray rubberized under coating	1.0	120.00	120.00 600
-	To remove and install rear suspension unit	1.0	200.00	200.00 7
-	To conduct wheel alignment	1.0	75.00	75.00 600
-	To remove and refit air con components and recharge air con gas	1.0	100.00	100.00 Mr's X
-	To install reverse sensor	1.0	40.00	40.00
-	To check wiring and lighting	1.0	60.00	60.00 400
-	To pull and realign rear chassis member	1.0	250.00	250.00
-	To remove and refit rear exhaust muffler	1.0	80.00	80.00 600
-	To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	2,400.00	2,400.00 21000
*	To remove and refit front/rear/LH/RH windscreen/door glass	1.0	2,000.00	2,000.00 14000
Spray Painting on a few parts				5,685.00

CONTINUE NEXT PAGE

Page 2 of 3