



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 070120

Contact : -

Fax No. : 6880 4838

Not Notarized
Clay &
Murray After Rain
18 days

Estimate : QUOT202106-000279(00)

Date : 09/06/2021

Vehicle No. : SLQ2896L

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Mileage (km) : 0

Chassis No. : MMBSTA13AHH006392

Accident Date : 06/06/2021 00:00:00

Claim No. : SLT6973E

Reference : JO202106-0402

Policy No. : 5101728531-02

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|--------------------|----------------------------|----------|------------|--------------------|
| NET ITEMS : | | | | |
| 1 | Rear bumper | 1.0 | 708.00 | mi 708.00 ✓ |
| 2 | Rear bumper retainer | 2.0 | 22.00 | cm 44.00 ✓ |
| 3 | Rear Bumper clips | 10.0 | 5.00 | na 50.00 ✓ |
| 4 | Rear bumper shield | 2.0 | 38.00 | ol/mi 76.00 ✓ |
| 5 | Rear bumper reflector | 2.0 | 20.00 | mi 40.00 ✓ |
| 6 | Rear RH fender | 1.0 | 715.00 | R 715.00 ✓ |
| 7 | Rear RH fender inner trim | 1.0 | 158.00 | Reform 158.00 ✓ |
| 8 | RH taillamp | 1.0 | 276.00 | Ro 276.00 ✓ |
| 9 | RH taillamp panel | 1.0 | 89.00 | R 89.00 ✓ |
| 10 | RH taillamp clip holder | 1.0 | 5.00 | na 5.00 ✓ |
| 11 | Rear end panel | 1.0 | 402.00 | R 402.00 ✓ |
| 12 | Rear end panel top garnish | 1.0 | 64.00 | su 64.00 X |
| 13 | Rear floor panel | 1.0 | 906.00 | R 906.00 ✓ |
| 14 | Rear exhaust muffler | 1.0 | 571.00 | SVC 571.00 7X |
| 15 | Rear RH rim | 1.0 | 710.00 | Per 710.00 X |
| 16 | Rear RH wheel bearing | 1.0 | 114.00 | na 114.00 X |
| 17 | Rear RH shock absorber | 1.0 | 204.00 | sha 204.00 X |
| 18 | Rear axle beam | 1.0 | 959.00 | su 959.00 X |
| 19 | Rear RH door lock | 1.0 | 290.00 | R 290.00 X |
| 20 | Front bumper | 1.0 | 666.00 | R 666.00 ✓ |
| 21 | Front bumper tow cover | 1.0 | 36.00 | na 36.00 ✓ |
| 22 | Front bumper lower grille | 1.0 | 156.00 | di 156.00 ✓ |
| 23 | Front bumper clip | 10.0 | 5.00 | na 50.00 ✓ |
| 24 | Front bumper tow cover | 1.0 | 36.00 | Agua 36.00 X |
| 25 | Front bumper retainer | 2.0 | 22.00 | SVC 44.00 7X |
| 26 | Front bumper reinforcement | 1.0 | 139.00 | R 139.00 ✓ |
| 27 | Front grille | 1.0 | 525.00 | 525.00 7X |
| 28 | Front grille logo | 1.0 | 42.00 | SVC { 42.00 7X |
| 29 | Rh Fog Lamp | 1.0 | 274.00 | 274.00 7X |
| 30 | Rh Fol Lamp cover | 1.0 | 120.00 | su 120.00 X |
| 31 | Headlamp | 2.0 | 544.00 | ol/m/cm 1,088.00 ✓ |
| 32 | Front support panel | 1.0 | 1,058.00 | R 1,058.00 X |
| 33 | Air con condenser | 1.0 | 683.00 | su 683.00 X |
| 34 | Air con discharge pipe | 1.0 | 190.00 | su 190.00 X |
| 35 | Air con liquid pipe | 1.0 | 275.00 | su 275.00 X |

CONTINUE NEXT PAGE

Page 1 of 3



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

Estimate : QUOT202106-000279(00)

Date : 09/06/2021

Vehicle No. : SLQ2896L

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Mileage (km) : 0

Chassis No. : MMBSTA13AHH006392

Accident Date : 06/06/2021 00:00:00

Claim No. : SLT6973E

Reference : JO202106-0402

Policy No. : 5101728531-02

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|-------------------------------|--|----------|------------|--------------------|
| 36 | Radiator | 1.0 | 872.00 | 872.00 X |
| 37 | Fan cowling | 1.0 | 117.00 | 117.00 X |
| 38 | Fan motor | 1.0 | 374.00 | 374.00 X |
| 39 | Fan blade | 1.0 | 70.00 | 70.00 X |
| 40 | Radiator upper air guide | 1.0 | 106.00 | 106.00 CM |
| 41 | Radiator lower air guide - LH | 1.0 | 18.00 | 18.00 CM |
| 42 | Radiator lower air guide - RH | 1.0 | 18.00 | 18.00 X |
| 43 | Rear keyless entry buzzer | 1.0 | 92.00 | 92.00 X |
| List Total : | | | | 13,430.00 |
| 10% Discount S\$ | | | | 1,343.00 |
| | | | | 12,087.00 |
| SPECIAL NET : | | | | |
| 1 | Reverse sensor | 1.0 | 250.00 | 250.00 Mr's 200.00 |
| 2 | Rear windscreen glass sealant | 1.0 | 40.00 | 40.00 Mr's |
| 3 | Insulator paste | 1.0 | 40.00 | 40.00 Mr's |
| 4 | Off - peak vehicle license plate seal | 1.0 | 20.00 | 20.00 Mr's |
| SPECIAL NET Total S\$: | | | | 350.00 |
| LABOUR : | | | | |
| - | To remove and refit rear trims, seats and upholstery | 1.0 | 120.00 | 120.00 100.00 |
| * | To remove and refit rear windscreen glass | 1.0 | 150.00 | 150.00 120.00 |
| - | To supply panel sealant and to seal off all weld spot seams and gaps | 1.0 | 90.00 | 90.00 |
| - | To spray rubberized under coating | 1.0 | 120.00 | 120.00 60.00 |
| - | To remove and install rear suspension unit | 1.0 | 200.00 | 200.00 nn 7 X |
| - | To conduct wheel alignment | 1.0 | 75.00 | 75.00 60.00 |
| - | To remove and refit air con components and recharge air con gas | 1.0 | 100.00 | 100.00 nn X |
| - | To install reverse sensor | 1.0 | 40.00 | 40.00 |
| - | To check wiring and lighting | 1.0 | 60.00 | 60.00 40.00 |
| - | To pull and realign rear chassis member | 1.0 | 250.00 | 250.00 |
| - | To remove and refit rear exhaust muffler | 1.0 | 80.00 | 80.00 60.00 |
| - | To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts | 1.0 | 2,400.00 | 2,400.00 2100.00 |
| * | To remove and refit front/rear/LH/RH windscreen/door glass | 1.0 | 2,000.00 | 2,000.00 1400.00 |
| Spray Painting on a few parts | | | | 5,685.00 |

CONTINUE NEXT PAGE

Page 2 of 3