

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00
SPRINGLEAF TOWER SINGAPORE 079909
MOTOR CLAIMS DEPT
ATTENTION:
CONTACT: 62222366 FAX NO: 62221033

EST/QUOTE NO. SQ006654

DATE: 09/06/2021
ACCIDENT DATE: 07/06/2021
VEHICLE NO: SKX6175H
CHASSIS/ENG.NO: MR053REH104542642
VEHICLE MODEL: TOYOTA ALTIS
CLAIM NO: SNM21D203271/C02
POLICY NO:
REMARK: 6175CHINA TP AGST
GBJ4414L

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER <i>torn</i>	511.20	25	383.40	383.40
2	<i>1 pc</i>	PC	FRT BUMPER SIDE RETAINER <i>scr / RH</i>	171.45	25	<i>128.59</i>	257.18 X
3	1	PC	FRT BUMPER LOWER GRILLE <i>XM</i>	182.10	25	136.57	136.57 X
4	1	PC	FRT BUMPER SPONGE <i>CM</i>	191.60	25	143.70	143.70
5	1	PC	FRT GRILLE <i>ms</i>	571.25	25	428.44	428.44
6	1	PC	FRT GRILLE EMBLEM <i>ms</i>	121.35	25	91.01	91.01
7	2	PC	FRT HEADLAMP <i>CM</i> <i>2271</i>	2,998.80	25	<i>1703.25</i> 2,249.85	<i>3406.50</i> 4,499.70
8	2	PC	FRT HEADLAMP CHROME TRIM <i>scr</i>	171.80	25	128.85	257.70
9	1	PC	FRT BRACE PANEL <i>repair</i>	182.25	25	136.69	136.69 X
						<i>4839.34</i>	
						SUB-TOTAL:	6,334.39
** NETT PRICE **							
1	10	PC	FRT BUMPER CLIPS <i>ms</i>	4.00	10	3.60	36.00
2	6	PC	FRT GRILLE CLIP <i>ms</i>	4.00	10	3.60	21.60
3	10	PC	FRT BONNET INSULATOR CLIPS <i>XM</i>	4.00	10	3.60	36.00 X
						SUB-TOTAL	93.60
** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE <i>X</i> <i>ms</i>	35.00		35.00	35.00 X
						SUB-TOTAL	35.00

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & OE

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00
SPRINGLEAF TOWER SINGAPORE 079909
MOTOR CLAIMS DEPT
ATTENTION :
CONTACT : 62222366 FAX NO: 62221033

EST/QUOTE NO. SQ006654

DATE : 09/06/2021
ACCIDENT DATE : 07/06/2021
VEHICLE NO : SKX6175H
CHASSIS/ENG.NO : MR053REH104542642
VEHICLE MODEL : TOYOTA ALTIS
CLAIM NO : SNM21D203271/C02
POLICY NO :
REMARK : 6175CHINA TP AGST
GBJ4414L

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

**** WORK LABOUR ****

TO KNOCK FRT BONNET, FRT FENDER X2, WELD, REMOVE & FIX
ON ABOVE PARTS
TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS
TO CHECK WIRING
TO APPLY ANTI RUST COATING
TO DIAGNOSE & RESET FAULT CODE
TOWING CHARGE *receipt? /*

1310

0.00	0.00
700.00	400 700.00
800.00	750 800.00
30.00	30.00
80.00	80.00 80.00
180.00	80 180.00
50.00	50.00 50.00
SUB-TOTAL 1,840.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

45 P/P
10/06/21 @ 1115
Roz after repair

4839.34
57.60
1310.00
6206.94

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 8,302.99
ADD 7% GST. S\$ 581.21
GRAND TOTAL : S\$ 8,884.20

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.