

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

9-Jun-21

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1405 T

|       |  |    |          |         |
|-------|--|----|----------|---------|
|       |  | \$ | 362.61   | NR      |
| 1 pc  | Tailgate lower garnish                       |    |          |         |
| 1 pc  | Emblem I30                                   | \$ | 27.80    | NEC     |
| 1 pc  | Emblem CRDI                                  | \$ | 29.40    | NEC     |
| 1 pc  | Rear bumper                                  | \$ | 811.11   | CRK     |
| 1 pc  | Rear bumper sponge                           | \$ | 79.20    | ? XSVL  |
| 1 pc  | Rear bumper reinforcement                    | \$ | 815.64   | ? XSVL  |
| 1 pc  | Rear bumper reinforcement centre             | \$ | 79.20    | ? XSVL  |
| 2 pcs | Rear bumper n/s & o/s side bracket @ \$52.20 | \$ | 104.40   | ? XSVL  |
| 2 pcs | Rear bumper n/s & o/s reflector @ \$107.50   | \$ | 215.00   | ? XSVL  |
|       |  | \$ | 2,524.36 | 868.31  |
|       |  | \$ | 504.87   |         |
|       |  | \$ | 2,019.49 | 694.64  |
|       |  | \$ | 48.00    | NEC     |
|       |  | \$ | 280.00   | XSVL    |
|       |  | \$ | 100.00   | NEC     |
|       |  | \$ | 50.00    | XNV     |
|       |  | \$ | 120.00   | 30      |
|       |  | \$ | 180.00   | XNV     |
|       |  | \$ | 750.00   | 360.    |
|       |  | \$ | 600.00   | 280     |
|       |  | \$ | 120.00   | 40      |
|       |  | \$ | 4,267.49 | 1552.64 |

**LKK Auto Consultants hence notify**  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

**S/NETT**

|       |                   |  |  |  |
|-------|-------------------|--|--|--|
| 1 set | Rear bumper clips |  |  |  |
| 1 set | Reverse sensor    |  |  |  |
| 1 set | Tailgate stickers |  |  |  |
|       | Sundry            |  |  |  |

- To dismantle and replace reverse sensor and test system
- To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.
- To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same etc
- To putty and spray painting on the rear bumper, tailgate lower garnish, end panel
- To apply rustproofing on the repaired and replaced panels

PARTS \$868.31  
LESS 20% \$173.66  
S/NETT \$694.65  
LABOUR \$710.00  
TOTAL \$1552.65  
LESS  
LIS 20% \$1242.12  
LIS \$1,200.00 / 3 REPAIR DAYS  
TOTAL

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

NAZ LKX  
10/6/2011 1415  
LIS  
CHECK ITEM PHOTO  
AFTER REPAIR PHOTO  
30 Days