



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 4287H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,878.30	1,782.30
1	SET REAR RH DOOR BLACK STICKER (CONSISTENT)	NECESSARY	38.00	38.00
1	SET REAR RH DOOR INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR RH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,892.00	-
1	REAR RH FENDER 1/4 GLASS MOULDING (CONSISTENT)	NOT NECESSARY	53.00	-
1	RH ROCKER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,799.60	-
	LESS 20% DISCOUNT		-1,142.18	-364.06
			4,568.72	1,456.24
SPECIAL NETT ITEMS				
1	SET REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
			50.00	-
LABOUR				
	LABOUR CHARGES FOR REMOVE/REFIT ,PANEL BEAT AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF REAR RH DOOR ,REAR RH FENDER AND RH ROCKER PANEL .		800.00	400.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		800.00	600.00
	TO REMOVE,REFIT REAR WINDSCREEN GLASS .	NOT NECESSARY	140.00	-
	TO REMOVE,REFIT REAR RH FENDER 1/4 GLASS .	NOT NECESSARY	80.00	-
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.		80.00	30.00
	REMOVE & REFIX DOOR ROCKER.		100.00	60.00
			2,000.00	1,090.00
GRAND TOTAL			6,618.72	2,546.24
RECOMMENDED COST OF REPAIRS				2,546.24

Report Ref No. CC4/ASM21006564/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.