

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SME4287H

No.	Qty	List Items	
1	1	Rear RH door	\$ <i>n</i> 1,878.30 ?
2	1 set	Rear RH door black sticker	\$ 38.00 ?
3	1 set	Rear RH door inner trim board clips	\$ <i>nn</i> 50.00 X
4	1	Rear RH fender	\$ <i>n</i> 1,892.00 X
5	1	Rear RH fender 1/4 glass moulding	\$ <i>nn</i> 53.00 X
6	1	RH rocker panel	\$ <i>n</i> 1,799.60 X
			\$ 5,710.90
			Less 20% \$ 1,142.18
Total :			\$ 4,568.72

Special Nett Items

7	1 set	Rear windscreen sealant	\$ <i>nn</i> 50.00 X
---	-------	-------------------------	----------------------

Labour

1		Labour Charges for remove/refit, panel beat and replacement of damages.	\$ 800.00 <i>400</i>
2		To putty and spray Spray Paintings charges.	\$ 800.00 <i>600</i>
3		To remove. Refit rear windscreen glass.	\$ <i>nn</i> 140.00 X
4		To remove, refit rear RH fender 1/4 glass.	\$ <i>nn</i> 80.00 X
5		To supply and apply anti rust treatment	\$ 80.00 ?
Total :			\$ 1,900.00

Total Parts and Labour : \$ 6,518.72

*Not Authorised
Repair By pain 3-4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: