



QUOTATION

Customer :

NO. : 38526

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPT

*not Actual
see
P/P = 1033
1/2 days
10/6/21
Edwards After rep.*

DATE : 09/06/2021
CLAIM NO. : 11740
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBL1663T
MAKE/MODEL : BMW / R1200GS

S. nett iten
(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BACK REST SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$216.00	216.00 <i>see</i>
2	BOX ALUMINIUM (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,395.00	1,395.00 <i>DD / Danged</i>
3	LABEL SPEED/PAYLOAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 <i>see</i>
4	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$63.00	63.00 <i>45</i>

SUB TOTAL 1,712.00
GST @ 7% 119.84
GRAND TOTAL (SGD) 1,831.84

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By

*P-988 s/w
L-45
1033*



RAYMOND

*38526 *

LLKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38526 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 38526 - Rev. 1

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPT

DATE : 09/06/2021
CLAIM NO. : 11740
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBL1663T
MAKE/MODEL : BMW / R1200GS

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX ALUMINIUM (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$950.00	950.00
2	LABEL SPEED/PAYLOAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
3	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$45.00	45.00
SUB TOTAL					\$1,033.00
GST @ 7 %					\$72.31
GRAND TOTAL (SGD)					\$1,105.31

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38526 *



Address: No. 6, Dafu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 203-14383
ISO 9001:2015