

AAD2106-022

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5343L

*Not Authorised**Recovery By paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 JUN 2021

SHD5343L

JTDKB3FU203078888

TOYOTA

PRIUS

04/06/2021

CHINA

11/01/2019

| PART                                     | LIST              |                 |
|------------------------------------------|-------------------|-----------------|
| 1 LENS AND BODY, REAR LAMP, RH           | \$ S <sub>n</sub> | 502.00          |
| 1 LENS & BODY, REAR COMBINATION LAMP, RH | \$ S <sub>n</sub> | 451.80          |
| 1 FENDER SUB-ASSY, FRONT RH              | \$ R              | 977.80          |
| 1 PANEL SUB-ASSY, QUARTER, RH            | \$ R              | 871.50          |
| 1 LINER, REAR WHEEL HOUSE, RH            | \$ S <sub>n</sub> | 139.80          |
| 1 COVER, REAR BUMPER                     | \$ R              | 442.60          |
| 1 FILLER, REAR BUMPER EXTENSION, RH      | \$ S <sub>n</sub> | 123.70          |
| 1 GUARD, REAR BUMPER, CENTER             | \$ S <sub>n</sub> | 576.30          |
| 1 REINFORCEMENT SUB-ASSY, REAR BUMPER    | \$ R              | 332.70          |
| <b>TOTAL</b>                             | <b>\$</b>         | <b>4,418.20</b> |
| <b>25%</b>                               | <b>\$</b>         | <b>1,104.55</b> |
|                                          | <b>\$</b>         | <b>3,313.65</b> |

**Special Nett**

|                             |                   |                 |
|-----------------------------|-------------------|-----------------|
| 1 FENDER LINER CLIP         | \$ R <sub>n</sub> | 75.00 X         |
| 1 FENDER CLIP               | \$ R <sub>n</sub> | 75.00 X         |
| 1 REAR BUMPER CLIP          | \$ R <sub>n</sub> | 65.00 X         |
| 1 END PANEL INNER TRIM CLIP | \$ R <sub>n</sub> | 60.00 X         |
| 1 TYRE                      | \$ S <sub>n</sub> | 350.00 X        |
| 1 RIM                       | \$ S <sub>n</sub> | 1,879.40 X      |
| 1 HUM CAP                   | \$ S <sub>n</sub> | 211.50 X        |
| <b>TOTAL</b>                | <b>\$</b>         | <b>2,715.90</b> |
| <b>TOTAL PARTS</b>          | <b>\$</b>         | <b>6,029.55</b> |

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ R<sub>n</sub> 250.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5343L**

|                                                                                                                           |           |                  |      |
|---------------------------------------------------------------------------------------------------------------------------|-----------|------------------|------|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$        | 1,800.00         | 4401 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$        | ~ 380.00         | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$        | ~ 170.00         | X    |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        | 1,800.00         | 1001 |
| To check steering geometry and computer wheel alignment                                                                   | \$        | ~ 220.00         | X    |
| To transfer of rear fender panel fittings, attachment and perform water seepage test.                                     | \$        | ~ 170.00         | X    |
| <b>TOTAL</b>                                                                                                              | <b>\$</b> | <b>4,790.00</b>  |      |
| <b>Over All Total</b>                                                                                                     | <b>\$</b> | <b>10,819.55</b> |      |

**(PART-BY-PART) Repair Days****10 Days****1 1/2 day****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer****Signature:****Date:**