

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5047Y**AAD2106-***Not Authorized
Return Bk paint***\$ 2158.93**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 JUN 2021**SHC5047Y**

JTDKB3FU703092639

TOYOTA

PRIUS **GEN 4**

07/06/2021

AIG.
06/11/2020**PART**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1

LIST		
\$	<i>Bu</i>	485.60 ✓
\$	<i>By</i>	332.70 ✓
\$	<i>ndlw</i>	374.50 ✓
\$	<i>nd</i>	22.00 ✓
\$	<i>Ln</i>	132.60
\$	<i>Ln</i>	132.60
\$	<i>Ln</i>	39.00
\$	<i>Ln</i>	39.00
\$	<i>R</i>	651.00
\$	<i>Ln</i>	126.70
\$	<i>Ln</i>	241.90
\$	<i>Ln</i>	175.10
\$	<i>Ln</i>	229.90
\$	<i>R</i>	1,147.80
\$	<i>R</i>	913.60
\$	<i>Ln</i>	242.50
\$	<i>Ln</i>	242.50
\$	<i>R</i>	61.00
\$	<i>R</i>	61.00
\$	<i>Ln</i>	47.90 ✓
\$	<i>Ln</i>	54.60 ✓
\$	<i>Ln</i>	54.60 ✓

TOTAL	\$	5,808.10
25%	\$	1,452.03
	\$	4,356.08

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5047Y**AAD2106-****Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

1 BUMPER CENTRE GUARD CLIP

1 REAR BUMPER PROTECTOR

1 REAR BUMPER RETAINER CLIP

1 BOOT STICKER TRANSCAB

1 BOOT STICKER 65553333

2 WINDSCREEN SEALANT

1 WINDSCREEN MOULDING

1 WINDSCREEN INNER SPONGE SEAL

\$	Adliser	700.00	220sal
\$	nn	85.00	50sal
\$	nn	80.00	X
\$	nsp	180.00	X
\$	nn	75.00	X
\$	nn	100.00	30sal
\$	nn	100.00	30sal
\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	130.00	X
TOTAL		\$ 1,120.00	

TOTAL PARTS \$ 5,476.08**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 300 4

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ nn 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 440

To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2106-**SHC5047Y**

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To Check Electrical Lighting Concerned.

\$ 170.00 *101***TOTAL \$ 4,840.00****Over All Total \$ 10,316.08****(PART-BY-PART) Repair Days****10 Days***2 days***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: