

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5047Y*Not Authored
Resumy B4part*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

PART

- 08 JUN 2021
- 1 COVER, REAR BUMPER
 - 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
 - 1 GUARD, REAR BUMPER, CENTER
 - 1 COVER, REAR BUMPER, LOWER
 - 1 RETAINER, REAR BUMPER SIDE, LH
 - 1 RETAINER, REAR BUMPER SIDE, RH
 - 1 REFLECTOR ASSY, REFLEX, LH
 - 1 REFLECTOR ASSY, REFLEX, RH
 - 1 PANEL SUB-ASSY, BODY LOWER BACK
 - 1 COVER, DECK TRIM, REAR
 - 1 COVER, FLOOR UNDER, NO.2 (RH)
 - 1 COVER, FLOOR UNDER, NO.1 (LH)
 - 1 COVER, REAR FLOOR (CTR)
 - 1 PANEL SUB-ASSY, BACK DOOR
 - 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
 - 1 STAY ASSY, BACK DOOR, LH
 - 1 STAY ASSY, BACK DOOR, RH
 - 1 HINGE ASSY, BACK DOOR, LH
 - 1 HINGE ASSY, BACK DOOR, RH
 - 1 ORNAMENT SUB-ASSY, BACK DOOR
 - 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
 - 1 PLATE, BACK DOOR NAME, NO.1

SHC5047Y

JTDKB3FU703092639

TOYOTA

PRIUS GEN 4

07/06/2021

AIG.

06/11/2020

LIST

\$	Bu	485.60	✓
\$		332.70	✓
\$	nd/lw	374.50	✓
\$	nd	22.00	✓
\$	SL	132.60	} X
\$	SL	132.60	
\$	SL	39.00	
\$	SL	39.00	
\$	R	651.00	
\$	SL	126.70	
\$	SL	241.90	
\$	SL	175.10	
\$	SL	229.90	
\$	R	1,147.80	
\$	R	913.60	} ✓
\$	SL	242.50	
\$	SL	242.50	
\$	R	61.00	
\$	R	61.00	} ✓
\$	nd	47.90	
\$	nd	54.60	
\$	nd	54.60	✓

TOTAL \$ 5,808.10**25% \$ 1,452.03****\$ 4,356.08**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5047Y**Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

1 BUMPER CENTRE GUARD CLIP

1 REAR BUMPER PROTECTOR

1 REAR BUMPER RETAINER CLIP

1 BOOT STICKER TRANSCAB

1 BOOT STICKER 65553333

2 WINDSCREEN SEALANT

1 WINDSCREEN MOULDING

1 WINDSCREEN INNER SPONGE SEAL

\$	ndllsr	700.00	220sal
\$	nn	85.00	50sal
\$	nn	80.00	X
\$	nsp	180.00	X
\$	nn	75.00	X
\$	nn	100.00	30sal
\$	nn	100.00	30sal
\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	130.00	X
TOTAL	\$	1,120.00	

TOTAL PARTS \$ 5,476.08**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 30q

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ nn 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 44q

To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

AAD2106-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5047Y

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

TOTAL \$ 4,840.00

Over All Total \$ 10,316.08

(PART-BY-PART) Repair Days

~~10 Days~~

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: