

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6721-9016 Fax : 6844-5185

Reg : 201838521G

Vehicle Number : SMY8967Y

Vehicle Model : OPEL CORSA

Accident Date : 04/06/2021

Original Reg Date : 29/3/2021

Date : 09/06/2021

Chassis : VXXKUPHNSSL4280811

TP Ins. AIG INS

Justin.

ESTIMATE

1	RR BUMPER	ton		\$ 1,597.00	✓
1	RR BUMPER SIDE RETAINER RH(outer)	new	could	\$ 199.00	✓
1	RR BUMPER REFLECTOR COVER RH	new		\$ 220.00	+
1	RR BUMPER PARKING SENSOR HOLDER (1 set 4pcs)	new		\$ 239.00	2
1	RR BUMPER BLIND SPOT SENSOR HOLDER(1 set 2pcs)	new		\$ 233.00	+
1	RR BUMPER BLIND SPOT SENSOR	new		\$ 316.00	+
1	RR BUMPER REVERSE SENSOR WIRE HARNESS	new		\$ 360.00	+
1	RR BUMPER MUD FLAT RH	cut		\$ 216.00	✓
1	RR TAILLAMP RH	new		\$ 631.00	+
1	RR BUMPER REFLECTOR RH	new		\$ 126.00	+
1	RR FENDER RH	Buckled.		\$ 1,951.00	✓
1	RR FENDER INNER SHIELD RH	new ton		\$ 321.00	+
1	RR WHEELHOUSE PANEL RH	Regis		\$ 1,531.00	+
1	RR FENDER TOP GARNISH RH	new		\$ 192.00	+
1	RR RIM RH	cut		\$ 898.00	✓
1	RR RIM CAP RH - GREY	new cut		\$ 157.00	+
1	RR ABS SENSOR	new		\$ 387.00	+
1	RR SHOCK ABSORBER RH	new		\$ 444.00	+
1	RR SHOCK ABSORBER TOP MOUNTING RH	new		\$ 182.00	+
1	RR SHOCK ABSORBER DUST COVER RH	new		\$ 211.00	+
1	RR WHEEL BEARING RH	new		\$ 349.00	2
1	RR AXLE ASSY	new		\$ 2,216.00	+

6160

5544

\$ 12,976.00

Less 10% \$ 1,297.60

\$ 11,678.40

Special Nett

1	1 pc	Rr Number Plate with Cover	new	\$ 65.00	+
2	10 pc	Rr Bumper Clip	new	\$ 50.00	✓
3	10 pc	Rr Fender Inner Shield Clip	new	\$ 60.00	+
4	10 pc	Rr fender protector clip	new	\$ 60.00	+
5	1 pc	Rr tyre rh	new	\$ 350.00	+
6	1 pc	Body Panel Joint Sealer	new	\$ 120.00	60

Labour charge

110

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,200.00
Carry out spray painting on accident affected area, RR DOOR RH, RR FENDER RH, RR BUMPER	\$ 1,200.00
To conduct anti rust of under carriage tuff coat	\$ 80.00
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 200.00
To remove and refix rear sensor and conduct test	\$ 100.00
To remove and refix reverse camera and conduct test	\$ 100.00
To conduct water leakage test after repairs of vehicle	\$ 60.00
Remove and replace RHR under carriage parts	\$ 400.00
To conduct 4 wheel alignment	\$ 180.00
To perform diagnosis reset on faulty code	\$ 350.00

1650

Total \$ 16,373.40

GST 7% \$ 1,146.14

Grand Total \$ 17,519.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P ~~17~~ 09/06/21
05 Dyr.

total: 7304.
(P/P)