

SIQ2971B. 2009 April

Mini Cooper S. 1598cc

WMWMS32050TJ92649.

TP AXA

Jasper.

Rear Number Plate	Rhd	30(SW) ✓
Rear Number Plate Holder.	Rhd	30(SW) ✓
Rear Bumper.	Distorted	989 ✓
Rear Bumper Clips.	per	50(SW) ✓
Rear Bumper Side Holder	x02 Dented	90x2=180 ✓
Rear Bumper lower Garnish	Rhd	295 ✓
Rear Bumper Grille	Distorted	280 ✓
Rear Bumper Grille Reflector	x02 Cracked	145x2=290 ✓
Rear Bumper Tow Cover	Rhd	35 ✓
Rear Bumper Sponge.	Cracked	109 ✓
Rear Bumper Reinforcement	Dented	538 ✓
Reverse Sensor	x04 2 pieces	520
Reverse Sensor Wire Harness.	snapped	260x2=1040
		349 ✓
Rear End Panel.	Distorted	785 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJQ2971B.

Reer End Panel Top Garnish	each	205	/
Reer End Panel Air Vent x02	each	58x2=116	/
Reer End Panel Sealant	per	60(SN)	/
Taillap x02	LH each	395	
		395x2=790	
Taillap Outer Chrome x02	per	65x2=130	X
Tailgate Distal		1098	/
Tailgate Lock	each	295	/
Tailgate Weatherstripe	1st	289	/
Tailgate Outer Garnish	each	345	/
Tailgate Inner Trim Board	each	328	/
Tailgate Inner Trim Board clips	per	30(SN)	/
Mini Logo	2 per	115	/
Cooper S Emblem		180	/
Spare Tyre Panel Top Board	each	288	/
Reer Fender Inner Trim Board x02	per	245x2=490	X
Reer Fender Inner Trim Board clips	per	60(SN)	X

SJQ2971B.

Reer Fender Outer Protector x02 ^{could} 245x2=490
 Reer Fender Outer Protector clips. ^{rn} 30(SN) 155
 Reer Fender Inner Shield x02 ^{LH} 195x2=390
 Reer Fender Inner Shield clips. ^{rn} 60(SN) 30(SN)

9923
 8930.70
 S.N. 440

Reer Exhaust Pipe. Bent 879. -
 Reer Exhaust Mounting. ^{ren} 45 +
 Reer Exhaust Heat Shield. ^{Cupled} 135 -
 Reer LH Tyre. ^{lt} 280(SN) 180(SN)

Panel Beating 1400 1000
 Spray Painting. 1400 1000
 Wiring. 2550 50 30
 To remove reverse sensor 100 60
 To remove upholstery. 150 80
 To apply tuff coat. 150 80
 To transfer tailgate fittings. 150 80
 To remove convertible roof. 300 +
 To remove exhaust pipe. 230 100
 To perform diagnostic test 250 120

total: 11920.70
 2/S: 95K.
 09 Days.