

ASS. REC. BY:

REF:

AIG/ 21006573/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

894K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7-9 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 62687

Yr Regn:

C9, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Me Lito

114 CD1 c.c

2143

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

13174

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WIV 44760323744788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / R / m / STD A / R / m or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/5/21

D.O.I.

10/6/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)

DATE : 09/06/2021

POLICY NO : 999995580

VEH REG NO : GBK6268Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323744788

ENGINE NO : 65195035287754

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	950.00	950.00 ✓
2 Bonnet lower lock	1	120.00	120.00 ✓
3 Bonnet lock switch	1	130.00	130.00 ✓
4 Bonnet upper lock	1	48.00	48.00 ✓
5 Bonnet cable	1	48.00	48.00 ?
6 Support panel	1	325.00	325.00 ✓
7 Support panel top garnish	1	68.00	68.00 ✓
8 Support panel bracket - RH / LH	2	18.00	36.00 ✓
9 Brace panel	1	85.00	85.00 ✓
10 Headlamp - RH / LH	2	550.00	1,100.00 ?
11 Front bumper	1	580.00	580.00 ✓
12 Front bumper centre logo	1	98.00	98.00 ✓
13 Front bumper reinforcement	1	590.00	590.00 ?
14 Front bumper carrier - RH / LH	2	85.00	170.00 ?
15 Front bumper side retainer - RH / LH	2	58.00	116.00 ?
16 Front bumper bracket - RH / LH	2	560.00	1,120.00 ?
17 Front bumper side strut - RH / LH	2	58.00	116.00 ?
18 Front bumper towing cover	1	20.00	20.00 X
19 Front bumper clips	15	5.50	82.50 ✓
20 Front bumper under cover	1	110.00	110.00 ✓
21 Horn	1	98.00	98.00 ?
22 Air-con condenser	1	465.00	465.00 ✓
23 Air-con condenser mounting frame	1	105.00	105.00 ?
24 Air-con suction pipe	1	260.00	260.00 ?
25 Air-con discharge pipe	1	325.00	325.00 ?
26 Radiator assy	1	420.00	420.00 ?
27 Radiator auto fan assy	1	750.00	750.00 ?
28 Radiator guide - RH / LH	2	58.00	116.00 ?
29 Radiator lower cover	1	98.00	98.00 ?
30 Radiator top clips - RH / LH	2	12.00	24.00 ✓
31 Radiator top bearing - RH / LH	2	28.00	56.00 ✓
32 Radiator lower support - RH / LH	2	35.00	70.00 ?
33 Radiator lower cross member	1	260.00	260.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)

DATE : 09/06/2021

POLICY NO : 999995580

VEH REG NO : GBK6268Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323744788

ENGINE NO : 65195035287754

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
34 Inter-cooler assy	1	580.00	580.00 ?
35 Inter-cooler hose - RH / LH	2	195.00	390.00 ?
36 Oil cooler	1	455.00	455.00 ?
37 Oil cooler pipe	1	158.00	158.00 ?
38 Engine under cover	1	CM 220.00	220.00 ✓
39 Water pump assy	1	560.00	560.00 ?
40 Water pump pulley	1	220.00	220.00 ?
41 Belt tensioner	1	268.00	268.00 ?
42 Fan belt	1	55.00	55.00 ?
			11,865.50
		Add 10%	1,186.55
			13,052.05
SPECIAL NET			
43 Radiator coolant (tin)	2	30.00	Mr 60.00 ✓
44 Auto transmission fluid	2	60.00	Mr 120.00 ✓
45 Front number plate	1	40.00	Mr 40.00 ✓
			220.00
LABOUR			
46 To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas	1	150.00	150.00 100%
47 To check and rectify wiring systems	1	80.00	80.00 20%
48 To panel beat and straighten front chassis frame, front cross member, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00 600-900%
49 To lift-up engine and gear box to facilitates the repairs	1	1,200.00	1,200.00 ?
50 To putty and spray paint on affected areas	1	800.00	800.00 200%
51 To reset headlamp fault code	1	350.00	350.00 ?
			4,380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL S\$ 17,652.05

ADD GST @ 7% 1,235.64

GRAND TOTAL S\$ 18,887.69

SINGAPORE DOLLAR EIGHTEEN THOUSAND EIGHT HUNDRED EIGHTY-SEVEN AND CENTS SIXTY-NINE ONLY

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/05/2021 19:02 (SGT)
Date of Accident	22/05/2021 13:50 (SGT)
Exact Location of Accident	Near Choa Chu Kang Dr, Singapore
Additional Location Information	KJE Exit Choa Chu Kang Drive
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK6268Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	osman.affan@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Vito
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	0


INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	-

DRIVER

Name of Driver	KOK GUAN SHENG
NRIC No	SXXXX899I

 Accident report SA0A215M0005



VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMMAD AZALY BIN ABDULLAH

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

22/5/21.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was entering the slip road towards Choa Chu Kang Drive from KJE Expressway. I saw a bike in the front of the slip road. I checked the main road and it was clear. I assume that the bike ahead of me had moved. But the bike was stationary. I moved forward slowly and rear needed the motorcycle.

I was shocked, but still manage to call an ambulance,
The rider was lightly injured.

Ambulance came but the rider insist he did not need to be conveyed to hospital

I asked the police if I need to make a police report, The police told me there is no need since the rider is not seriously injured.

We exchange particulars.

No serious injury involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 22052021

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMMAD AZALY BIN ABDULLAH
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: