



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)

DATE : 09/06/2021

POLICY NO : 999995580

VEH REG NO : GBK6268Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323744788

ENGINE NO : 65195035287754

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	950.00	B ₁ 950.00 ✓
2 Bonnet lower lock	1	120.00	D ₁₇ 120.00 ✓
3 Bonnet lock switch	1	130.00	D ₁₇ 130.00 ✓
4 Bonnet upper lock	1	48.00	D ₁₇ 48.00 ✓
5 Bonnet cable	1	48.00	Sn 48.00 X
6 Support panel	1	325.00	CM 325.00 ✓
7 Support panel top garnish	1	68.00	Per 68.00 ✓
8 Support panel bracket - RH / LH	2	18.00	c/s CM 36.00 ✓
9 Brace panel	1	85.00	B ₁ 85.00 ✓
10 Headlamp - RH / LH	2	550.00	NLS mgcm 1,100.00 Z
11 Front bumper	1	580.00	B ₁ 580.00 ✓
12 Front bumper centre logo	1	98.00	CM 98.00 ✓
13 Front bumper reinforcement	1	590.00	R 590.00 X
14 Front bumper carrier - RH / LH	2	85.00	NLS B ₁ 170.00 Z
15 Front bumper side retainer - RH / LH	2	58.00	Sn 116.00 X
16 Front bumper bracket - RH / LH	2	560.00	R 1,120.00 X
17 Front bumper side strut - RH / LH	2	58.00	NLS B ₁ 116.00 Z
18 Front bumper towing cover	1	20.00	B ₁ 20.00 X
19 Front bumper clips	15	5.50	SOSN 82.50 ✓
20 Front bumper under cover	1	110.00	B ₁ 110.00 ✓
21 Horn	1	98.00	CM 98.00 Z
22 Air-con condenser	1	465.00	B ₁ 465.00 ✓
23 Air-con condenser mounting frame	1	105.00	CM 105.00 Z
24 Air-con suction pipe	1	260.00	Sn 260.00 X
25 Air-con discharge pipe	1	325.00	Sn 325.00 X
26 Radiator assy	1	420.00	B ₁ 420.00 Z
27 Radiator auto fan assy	1	750.00	CM 750.00 Z
28 Radiator guide - RH / LH	2	58.00	CM 116.00 Z
29 Radiator lower cover	1	98.00	CM 98.00 Z
30 Radiator top clips - RH / LH	2	12.00	Sn 24.00 ✓
31 Radiator top bearing - RH / LH	2	28.00	D ₁₇ 56.00 ✓
32 Radiator lower support - RH / LH	2	35.00	NLS 70.00 Z
33 Radiator lower cross member	1	260.00	B ₁ 260.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)

DATE : 09/06/2021

POLICY NO : 999995580

VEH REG NO : GBK6268Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323744788

ENGINE NO : 65195035287754

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
34 Inter-cooler assy	1	Pr 580.00	580.00
35 Inter-cooler hose - RH / LH	2	Pr 195.00	390.00
36 Oil cooler	1	Pr 455.00	455.00
37 Oil cooler pipe	1	Sn 158.00	158.00
38 Engine under cover	1	CM 220.00	220.00
39 Water pump assy	1	Sn 560.00	560.00
40 Water pump pulley	1	Sn 220.00	220.00
41 Belt tensioner	1	Sn 268.00	268.00
42 Fan belt	1	Sn 55.00	55.00
			11,865.50
		Add 10%	1,186.55
			13,052.05
SPECIAL NET			
43 Radiator coolant (tin)	2	30.00	60.00
44 Auto transmission fluid	2	60.00	120.00
45 Front number plate	1	40.00	40.00
			220.00
LABOUR			
46 To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas	1	150.00	150.00
47 To check and rectify wiring systems	1	80.00	80.00
48 To panel beat and straighten front chassis frame, front cross member, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00
49 To lift-up engine and gear box to facilitates the repairs	1	1,200.00	1,200.00
50 To putty and spray paint on affected areas	1	800.00	800.00
51 To reset headlamp fault code	1	350.00	350.00
			4,380.00
		TOTAL	S\$ 17,652.05
		ADD GST @ 7%	1,235.64
		GRAND TOTAL	S\$ 18,887.69

SINGAPORE DOLLAR EIGHTEEN THOUSAND EIGHT HUNDRED EIGHTY-SEVEN AND CENTS SIXTY-NINE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)
DATE : 25/06/2021
POLICY NO : 999995580
VEH REG NO : GBK6268Z
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : W1V44760323744788
ENGINE NO : 65195035287754
REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Radiator spare tank	1 <i>ng Bu</i>	98.00	98.00 ✓
2 Radiator coolant pipe	1 <i>nd</i>	102.00	102.00 ✓
3 Oil sum	1 <i>nd/wap</i>	395.00	395.00 ✓
4 Oil pan	1 <i>CM</i>	750.00	750.00 ✓
5 Engine mounting - LH	1 <i>CM</i>	220.00	220.00 ✓
6 Engine mounting screw	1 <i>R</i>	8.00	8.00 ✓
			1,573.00
		Add 10%	157.30
			1,730.30
SPECIAL NET			
7 Oil sum gasket sealant	1 <i>nd</i>	25.00	25.00 ✓
8 Engine oil (litres)	4 <i>nd</i>	25.50	102.00 ✓
			127.00
TOTAL			S\$ 1,857.30
ADD GST @ 7%			130.01
GRAND TOTAL			S\$ 1,987.31

SINGAPORE DOLLAR ONE THOUSAND NINE HUNDRED EIGHTY-SEVEN AND CENTS THIRTY-ONE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE