

**TONG LUCK AUTO PTE LTD**

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)

DATE : 09/06/2021

POLICY NO : 999995580

VEH REG NO : GBK6268Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323744788

ENGINE NO : 65195035287754

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	950.00	950.00 ✓
2 Bonnet lower lock	1	120.00	120.00 ✓
3 Bonnet lock switch	1	130.00	130.00 ✓
4 Bonnet upper lock	1	48.00	48.00 ✓
5 Bonnet cable	1	48.00	48.00 ?
6 Support panel	1	325.00	325.00 ✓
7 Support panel top garnish	1	68.00	68.00 ✓
8 Support panel bracket - RH / LH	2	18.00	36.00 ✓
9 Brace panel	1	85.00	85.00 ✓
10 Headlamp - RH / LH	2	550.00	1,100.00 ?
11 Front bumper	1	580.00	580.00 ✓
12 Front bumper centre logo	1	98.00	98.00 ✓
13 Front bumper reinforcement	1	590.00	590.00 ?
14 Front bumper carrier - RH / LH	2	85.00	170.00 ?
15 Front bumper side retainer - RH / LH	2	58.00	116.00 ?
16 Front bumper bracket - RH / LH	2	560.00	1,120.00 ?
17 Front bumper side strut - RH / LH	2	58.00	116.00 ?
18 Front bumper towing cover	1	20.00	20.00 ✓
19 Front bumper clips	15	5.50	82.50 ✓
20 Front bumper under cover	1	110.00	110.00 ✓
21 Horn	1	98.00	98.00 ?
22 Air-con condenser	1	465.00	465.00 ✓
23 Air-con condenser mounting frame	1	105.00	105.00 ?
24 Air-con suction pipe	1	260.00	260.00 ?
25 Air-con discharge pipe	1	325.00	325.00 ?
26 Radiator assy	1	420.00	420.00 ?
27 Radiator auto fan assy	1	750.00	750.00 ?
28 Radiator guide - RH / LH	2	58.00	116.00 ?
29 Radiator lower cover	1	98.00	98.00 ?
30 Radiator top clips - RH / LH	2	12.00	24.00 ✓
31 Radiator top bearing - RH / LH	2	28.00	56.00 ✓
32 Radiator lower support - RH / LH	2	35.00	70.00 ?
33 Radiator lower cross member	1	260.00	260.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/05/2021

ESTIMATE

NO : QUOT202106-000029(00)

DATE : 09/06/2021

POLICY NO : 999995580

VEH REG NO : GBK6268Z

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323744788

ENGINE NO : 65195035287754

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : GBK6268Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
34 Inter-cooler assy	1	580.00	580.00 ?
35 Inter-cooler hose - RH / LH	2	195.00	390.00 ?
36 Oil cooler	1	455.00	455.00 ?
37 Oil cooler pipe	1	158.00	158.00 ?
38 Engine under cover	1	CM 220.00	220.00 ✓
39 Water pump assy	1	560.00	560.00 ?
40 Water pump pulley	1	220.00	220.00 ?
41 Belt tensioner	1	268.00	268.00 ?
42 Fan belt	1	55.00	55.00 ?
			11,865.50
		Add 10%	1,186.55
			13,052.05
SPECIAL NET			
43 Radiator coolant (tin)	2	30.00	60.00 ✓
44 Auto transmission fluid	2	60.00	120.00 ✓
45 Front number plate	1	40.00	40.00 ✓
			220.00
LABOUR			
46 To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas	1	150.00	150.00 100%
47 To check and rectify wiring systems	1	80.00	80.00 20%
48 To panel beat and straighten front chassis frame, front cross member, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00 600-900%
49 To lift-up engine and gear box to facilitates the repairs	1	1,200.00	1,200.00 ?
50 To putty and spray paint on affected areas	1	800.00	800.00 200%
51 To reset headlamp fault code	1	350.00	350.00 ?
			4,380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL S\$ 17,652.05

ADD GST @ 7% 1,235.64

GRAND TOTAL S\$ 18,887.69

SINGAPORE DOLLAR EIGHTEEN THOUSAND EIGHT HUNDRED EIGHTY-SEVEN AND CENTS SIXTY-NINE ONLY

Acknowledged by Repairer

Signature:

Date: