

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN TIEN HOCK
 BLK 117A RIVERVALE DRIVE #11-78
 SINGAPORE 541117

Contact : 84906666

TP Ching
 Xiao Chen.

ESTIMATE

Repair Code : CLM16840

Date in : 09/06/2021

Vehicle Num. : SLL1596K

Model : TOYOTA WISH 1.8 CVT

Chassis/Eng# : JTDGG20W90J006402/2ZR1908970

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	698.10	<i>492</i> ✓ 698.10
REAR BUMPER BRACKET L/R <i>new</i>	2	55.00	✓ 110.00
REAR BUMPER INNER WIRE HARNESS <i>new</i>	1	56.90	✓ 56.90
REAR BUMPER REFLECTOR L/R <i>new</i>	2	59.80	✓ 119.60
REAR BUMPER REVERSE SENSOR COVER L/R <i>new</i>	2	45.10	✓ 90.20
REAR BUMPER REVERSE SENSOR L/R <i>Dmgd</i>	2	235.50	✓ 471.00
REAR BUMPER SIDE BRACKET L/R <i>new</i>	2	46.00	✓ 92.00
REAR BUMPER SIDE RETAINER L/R <i>new L/R Dmgd</i>	2	97.40	<i>97.40</i> ✓ 194.80
REAR END LOWER PANEL <i>Repr</i>	1	375.00	✓ 375.00
REAR END PANEL <i>Dented</i>	1	540.80	✓ 540.80
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	192.20	✓ 192.20
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	298.00	✓ 298.00
REAR TAILGATE <i>Repr</i>	1	1477.30	✓ 1,477.30
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	72.50	✓ 72.50
REAR TAILGATE 'VALVE MATIC' EMBLEM <i>new</i>	1	51.10	✓ 51.10
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	412.70	✓ 412.70
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	335.70	✓ 335.70

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN TIEN HOCK
BLK 117A RIVERVALE DRIVE #11-78
SINGAPORE 541117

Contact : 84906666

ESTIMATE

Repair Code : CLM16840
Date in : 09/06/2021
Vehicle Num. : SLL1596K
Model : TOYOTA WISH 1.8 CVT
Chassis/Eng# : JTDGG20W90J006402/2ZR1908970

	Subtotal before discount	2550.70	5,587.90
Percentage discount 25%		1913.02	1,396.98
	Sub-total 1		4,190.93
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	10 20.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	+ 25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	+ 50.00
	Subtotal before discount		145.00
Percentage discount 0%			0.00
	Sub-total 2		145.00
	Parts-total		4,335.93

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

1340
50 ~~80.00~~
30 ~~100.00~~
600 ~~900.00~~
500 ~~1,000.00~~
60 ~~100.00~~

Labour Total 2,180.00

Parts & Labour Total 6,515.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 2 total: 3293.02
H/S: 2.6K / 10/06/21
05 days