

ASS. REC. BY:

Tangkh

REF:

CS3/CT12100 6583/TIVC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SMH 6393E

Policy No. DMHCSNA00004132000

Claims No. SNM21D203263/C02/TOHHS

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$78K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

W/ PRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG4140Z

Yr Regn:

2016, Sep.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

1798

Make:

Toyota Prius Hybrid

c.c

1797

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

102373

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4203535330

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

N

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A. 7/6/21

D.O.I.

10/6/21 103pm

Survey held at

A Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Range : \$4000 - \$6000 , 6 days
GIA uploaded in Views

11/6/21

Submit PRS, repair range \$4,000-\$6,000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 11/6/21-Typist

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / L.B.I. (\$