

Aspire 3

A314-32-C6Z5

DDR4



K9

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5607G

AAD2106-

Not Authored

Penny B4 part

8 14723.58

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 JUN 2021

SHC5607G

JTDKB3FU803093749

TOYOTA

PRIUS GEN 4

07/06/2021

Tokio

25/02/2021

	PART		LIST	
1	COVER, REAR BUMPER	\$	mgcM 485.60	✓
1	GUARD, REAR BUMPER, CENTER	\$	Sm 374.50	X
1	COVER, REAR BUMPER, LOWER	\$	Sm 22.00	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	Dir 132.60	✓
1	SEAL, REAR BUMPER SIDE, RH	\$	Sm 118.30	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	Sm 132.60	X
1	REFLECTOR ASSY, REFLEX, RH	\$	Sm 39.00	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R 651.00	X
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	R 1,294.90	✓
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	R 206.70	✓
1	LOCK ASSY, REAR DOOR W/MOTOR, RH	\$	Tm 561.90	✓
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	Dir 98.90	✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	Dir 87.10	✓
1	CHECK ASSY, REAR DOOR, RH	\$	Sm 183.80	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	Smc 97.40	X
1	COVER, REAR DOOR OUTSIDE HANDLE, RH	\$	Smc 17.90	X
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	Sm 193.50	X
1	HANDLE, DOOR PULL	\$	Sm 23.40	X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	CR 594.80	✓
1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$	R 343.40	X
1	LINER, REAR WHEEL HOUSE, RH	\$	Dir 139.80	✓
1	DUCT ASSY, QUARTER VENT, RH	\$	Sm 67.00	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	R 871.50	✓
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	Sm 339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	Sm 261.00	X
1	PANEL SUB-ASSY, BACK DOOR	\$	R 1,147.80	X

Trans-cab Auto Services Pte Ltd

AAD2106-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5607G

1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	Sn	913.60	
1	HINGE ASSY, BACK DOOR, LH	\$	K	61.00	
1	HINGE ASSY, BACK DOOR, RH	\$	K	61.00	
1	STAY ASSY, BACK DOOR, LH	\$	Sn	242.50	
1	STAY ASSY, BACK DOOR, RH	\$	Sn	242.50	
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	na	47.90	
1	PLATE, BACK DOOR NAME, NO.1	\$	na	54.60	
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	na	54.60	
1	AIR BAG ASSY, CURTAIN SHIELD, RH	\$	Burn	1,748.10	✓
1	SENSOR ASSY, SIDE AIR BAG, RH, NO.2	\$	na	709.30	✓
1	SENSOR, DOOR SIDE AIR BAG, RH	\$	Sn	379.20	X
1	SENSOR ASSY, SIDE AIR BAG, RH	\$	Sn	567.80	X
1	COMPUTER ASSY, AIR BAG	\$	na	1,546.00	✓
1	BELT ASSY, REAR SEAT, OUTER CENTER	\$	Sn	628.10	X
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	Sn	995.10	✓
1	BELT ASSY, REAR SEAT, INNER W/CENTER, LH	\$	Sn	251.60	X
1	BELT ASSY, REAR SEAT, INNER	\$	Sn	150.70	X
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	Sn	995.10	✓
TOTAL		\$		18,134.70	
25%		\$		4,533.68	
		\$		13,601.03	

Special Nett

1	REAR BUMPER SIDE CLIP	\$	na	60.00	505a
1	SET PARKING AID	\$	Sn	700.00	X
1	SET REAR BUMPER CLIP	\$	na	85.00	X
1	REAR BUMPER RETAINER CLIP	\$	na	75.00	X
1	SET REAR FENDER LINER CLIP	\$	na	75.00	X
1	TYRE	\$	Sn	350.00	X
1	HUB CAP	\$	mis	211.50	✓
1	RIM	\$	Od	1,879.40	✓
1	REAR DOOR STICKER '6555-3333'	\$	na	100.00	605a
1	REAR BOOT STICKER '6555-3333'	\$	Approved	100.00	X
1	REAR BOOT STICKER 'TRANSCAB'	\$	na	100.00	X

Trans-cab Auto Services Pte Ltd**AAD2106-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5607G

2	WINDSCREEN SEALANT	\$	nn	150.00	X
1	WINDSCREEN MOULDING	\$	nn	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X
1SET	TAILLAMP CLIP	\$	nn	50.00	X
1	WHEELHOUSE LINER CLIP	\$	nn	70.00	X
TOTAL		\$		995.00	

TOTAL PARTS \$ 14,596.03**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	60¢
To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	120¢
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	900¢
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00 X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	1100¢
To reinstall rear bumper parking sensor.	\$	170.00	50¢
To transfer of tire, rim and on wheel balancing.	\$	170.00	20¢
To Check Electrical Lighting Concerned.	\$	170.00	20¢

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5607G**AAD2106-**

To check steering geometry and computer wheel alignment \$ 220.00 60%

To remove and refit of rear fender fittings, attachment and perform water seepage test.

	\$	<i>Remove</i> 170.00 X
TOTAL	\$	5,400.00

Over All Total	\$	19,996.03
-----------------------	----	------------------

(PART-BY-PART) Repair Days **10 Days***8 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5607G

AAD2106- 038 -

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC5607G

JTDKB3FU803093749

TOYOTA

PRIUS GEN 4

07/06/2021

TOKIO

25/02/2021

SUPPLEMENTARY**PART**

- 1 HEADLINING ASSY, ROOF
- 1 BELT ASSY, FRONT SEAT OUTER, RH
- 1 BELT ASSY, FRONT SEAT OUTER, LH
- 1 BELT ASSY, FRONT SEAT INNER, RH
- 1 BELT ASSY, FRONT SEAT INNER, LH
- 1 SHAFT ASSY, FRONT DRIVE, RH
- 1 KNUCKLE, STEERING, RH
- 1 ARM ASSY, UPPER CONTROL, REAR RH
- 1 ARM ASSY, REAR SUSPENSION, NO.2 RH
- 1 ARM ASSY, REAR SUSPENSION, NO.1 RH
- 1 ABSORBER ASSY, SHOCK, REAR RH
- 1 LOCK ASSY, REAR DOOR W/MOTOR, RH
- 1 WIRE, REAR DOOR, NO.1
- 1 WIRE, REAR DOOR, NO.2
- 1 BOARD SUB-ASSY, REAR DOOR TRIM, RH
- 1 PILLAR, CENTER BODY, OUTER RH

LIST

\$	<i>By</i>	2,125.70	✓
\$	<i>Repaired</i>	995.10	X
\$	<i>"</i>	995.10	X
\$	<i>Sn</i>	177.00	X
\$	<i>Sn</i>	177.00	X
\$	<i>NIP</i>	1,379.50	X
\$	<i>By</i>	663.40	✓
\$	<i>Di</i>	420.80	✓
\$	<i>By</i>	497.50	✓
\$	<i>Di</i>	239.20	✓
\$	<i>By</i>	127.00	✓
\$	<i>Repaired</i>	561.90	X
\$	<i>Sn</i>	247.40	X
\$	<i>Sn</i>	247.40	X
\$	<i>Sn</i>	556.60	X
\$	<i>R</i>	323.10	X
TOTAL \$		9,733.70	
25% \$		2,433.43	
\$		7,300.28	