

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SMD2431B

Type of Claim : TPVehicle No. : SMD2431BMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RJ003280Ins Company : AIG ASIA PACIFIC
Excess : INSURANCE PTE LTD

Engine No. : _____

Date of Accident : 09/06/2021Policy No. : SD21V00611/VPZ/R01

Time of Accident : _____

Suggested Days of Repair : 8Case Owner : BLUECAR EAST ASIA PTE LTDTP Vehicle No. : SMY3138G**Repair Estimates**Parts (a) Cost / List Price Items \$ 8,284.00Plus/Less- 20.0% \$ 1,656.80Total of Cost / List \$ 9,940.80(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 276.00Total Parts Cost (Appendix A) \$ 10,216.80Labour (Appendix B) \$ 2,670.00Total Repair Cost \$ 12,886.80

not Authorized
take
the photo before repair
10/6/21
6 days.
HP 90096608

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SMD2431B Case Owner : BLUECAR EAST
Make & Model : BLUECAR Year Manufacture : ASIA PTE LTD
Chassis No : VL4BCEB4RJ003280 Engine No : 0
Date & Time : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/N	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT FENDER LH	1	\$ 1,037.00	\$ 1,037.00			Dis ✓
2	FRONT FENDER INNER SHIELD LH	1	\$ 154.00	\$ 154.00			Dis ✓
3	FRONT FENDER INNER SHIELD CLIPS	10	\$ 1.00	\$ 10.00			Dis ✓
4	FRONT FENDER COVER LH	1	\$ 194.00	\$ 194.00			Dis ✓
5	FRONT FENDER COVER NUTS	6	\$ 1.00	\$ 6.00			Dis ✓
8	FRONT BUMPER	1	\$ 1,493.00	\$ 1,493.00			Dis ✓
9	FRONT BUMPER CLIPS	10	\$ 1.00	\$ 10.00			Dis ✓
12	LH SIDE SKIRT	1	\$ 284.00	\$ 284.00			Dis ✓
13	FRONT STEEL RIM SET	1	\$ 254.00	\$ 254.00			Dis ✓
14	FRONT TYRE	1		\$ -			Dis ✓
15	FRONT TYRE PRESSURE SENSOR	1	\$ 142.00	\$ 163.00			Dis ✓
17	FRONT LEFT ABSORBER WITH MOUNTING	1	\$ 293.00	\$ 293.00			Dis ✓
18	ANTI ROLL TIE ROD LH	1	\$ 105.00	\$ 105.00			Dis ✓
19	STABILIZER BAR	1	\$ 240.00	\$ 240.00			Dis ✓
20	FRONT LH KNUCKLE ARM	1	\$ 400.00	\$ 400.00			Dis ✓
21	FRONT LH LOWER ARM	1	\$ 395.00	\$ 395.00			Dis ✓
22	DRIVE SHAFT LH	1	\$ 421.00	\$ 421.00			Dis ✓
24	STEERING RACK END	1	\$ 125.00	\$ 125.00			Dis ✓
25	LH DOOR	1	\$ 2,700.00	\$ 2,700.00			Dis ✓
26	LH DOOR STICKER	1					Dis ✓
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 8,240.00 \$ 8,284.00 \$ - \$ - \$276.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	259H
Vehicle Details	
Vehicle No.:	SMD2431B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2021
Vehicle Make:	BLUECAR
Vehicle Model:	BLUECAR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	-
Chassis No.:	VL4BCEB4RJT003280
Maximum Power Output:	50.0 kW (67 bhp)
Open Market Value:	\$33,708.00
Original Registration Date:	08 Aug 2018
First Registration Date:	08 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$19,192.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2028
PARF Rebate Amount:	\$14,394.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$24,480.00
Total Rebate Amount:	\$38,874.00

The information contained herein is correct as at 10 Jun 2021

OK