



No . 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SMD2431B

Type of Claim : TPVehicle No. : SMD2431BMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RJT003280Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTD

Engine No. : _____

Excess : _____

Policy No. : SD21V00611/VPZ/R01Date of Accident : 09/06/2021

Time of Accident : _____

Suggested Days of Repair : 8Case Owner : BLUECAR EAST ASIA PTE LTD**Repair Estimates**TP Vehicle No. : SMY3138GParts (a) Cost / List Price Items \$ 8,284.00Plus/Less— 20.0% \$ 1,656.80Total of Cost / List \$ 9,940.80(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 276.00Total Parts Cost (Appendix A) \$ 10,216.80Labour (Appendix B) \$ 2,670.00Total Repair Cost \$ 12,886.80*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No	: <u>SMD2431B</u>	Case Owner	: <u>BLUECAR EAST</u> <u>ASIA PTE LTD</u>
Make & Model	: <u>BLUECAR</u>	Year Manufacture	: <u>2017</u>
Chassis No	: <u>VL4BCEB4RJT003280</u>	Engine No	: <u>0</u>
Date & Time	: _____	Supplier	: _____
Order By	: _____	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT FENDER LH	1	\$ 1,037.00	\$ 1,037.00			
2	FRONT FENDER INNER SHIELD LH	1	\$ 154.00	\$ 154.00			
3	FRONT FENDER INNER SHIELD CLIPS	10	\$ 1.00	\$ 10.00			
4	FRONT FENDER COVER LH	1	\$ 194.00	\$ 194.00			
5	FRONT FENDER COVER NUTS	6	\$ 1.00	\$ 6.00			
8	FRONT BUMPER	1	\$ 1,493.00	\$ 1,493.00			
9	FRONT BUMPER CLIPS	10	\$ 1.00	\$ 10.00			
12	LH SIDE SKIRT	1	\$ 284.00	\$ 284.00			
13	FRONT STEEL RIM SET	1	\$ 254.00	\$ 254.00			
14	FRONT TYRE	1		\$ -			\$ 206.00
15	FRONT TYRE PRESSURE SENSOR	1	\$ 142.00	\$ 163.00			
17	FRONT LEFT ABSORBER WITH MOUNTING	1	\$ 293.00	\$ 293.00			
18	ANTI ROLL TIE ROD LH	1	\$ 105.00	\$ 105.00			
19	STABILIZER BAR	1	\$ 240.00	\$ 240.00			
20	FRONT LH KNUCKLE ARM	1	\$ 400.00	\$ 400.00			
21	FRONT LH LOWER ARM	1	\$ 395.00	\$ 395.00			
22	DRIVE SHAFT LH	1	\$ 421.00	\$ 421.00			
24	STEERING RACK END	1	\$ 125.00	\$ 125.00			
25	LH DOOR	1	\$ 2,700.00	\$ 2,700.00			
26	LH DOOR STICKER	1					\$ 70.00
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 8,240.00 \$ 8,284.00 \$ - \$ - \$276.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

**BLUECAR
EAST ASIA**

Case Owner

Year of Manufacture

: 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any