

Indeco

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

* Joslin

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SMD2431B

Type of Claim : TP

Vehicle No. : SMD2431B

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RJT003280

Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTD

Engine No. :

Excess :

Policy No. : SD21V00611/VPZ/R01

Date of Accident : 09/06/2021

Time of Accident :

Suggested Days of Repair : 8

Case Owner : BLUECAR EAST ASIA PTE LTD

TP Vehicle No. : SMY3138G

Repair Estimates

Parts (a) Cost / List Price Items \$ 8,284.00

Plus/Less- ~~20.0%~~ ^{15%} \$ 1,656.80

Total of Cost / List \$ 9,940.80

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 276.00

Total Parts Cost (Appendix A) \$ 10,216.80

Labour (Appendix B) \$ 2,670.00

Total Repair Cost \$ 12,886.80

The above total will be subjected to 7% G.S.T.

not Authorized
mak
take photo before repair
10/6/21
6 days.
HP 90096608
P/P & 8179.40

Name of Surveyor :

Company :

Survey conducted on : at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date: 8179.40

P-5556
+ 15% + 833.4
P-6389.40
S/N-110
L-1680
8179.40



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SMD2431B Case Owner : BLUECAR EAST
Make & Model : BLUECAR Year Manufacture : ASIA PTE LTD
Chassis No : VL4BCEB4RJT003280 Engine No : 0
Date & Time : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT FENDER LH	1	\$ 1,037.00	\$ / 1,037.00			Dys -
2	FRONT FENDER INNER SHIELD LH	1	\$ 154.00	\$ / 154.00			Dys -
3	FRONT FENDER INNER SHIELD CLIPS	10	\$ 1.00	\$ / 10.00			net -
4	FRONT FENDER COVER LH	1	\$ 194.00	\$ / 194.00			Dys -
5	FRONT FENDER COVER NUTS	6	\$ 1.00	\$ / 6.00			net -
8	FRONT BUMPER	1	\$ 1,493.00	\$ / 1,493.00			Dys -
9	FRONT BUMPER CLIPS	10	\$ 1.00	\$ / 10.00			net -
12	LH SIDE SKIRT	1	\$ 284.00	\$ / 284.00			Dys -
13	FRONT STEEL RIM SET	1	\$ 254.00	\$ 254.00			Surf 40 s/n
14	FRONT TYRE	1		\$ -		Surf \$ 206.00	X
15	FRONT TYRE PRESSURE SENSOR	1	\$ 142.00	\$ 163.00			12 X
17	FRONT LEFT ABSORBER WITH MOUNTING	1	\$ 293.00	\$ / 293.00			Ben/Sec -
18	ANTI ROLL TIE ROD LH	1	\$ 105.00	\$ / 105.00			Thw -
19	STABILIZER BAR	1	\$ 240.00	\$ 240.00			11 X
20	FRONT LH KNUCKLE ARM	1	\$ 400.00	\$ / 400.00			Ben -
21	FRONT LH LOWER ARM	1	\$ 395.00	\$ / 395.00			Surf -
22	DRIVE SHAFT LH	1	\$ 421.00	\$ / 421.00			Surf -
24	STEERING RACK END	1	\$ 125.00	\$ 125.00			11 X
25	LH DOOR	1	\$ 2,700.00	\$ 2,700.00			RX
26	LH DOOR STICKER	1				net \$ 70.00	✓ s/n
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 8,240.00 \$ 8,284.00 \$ - \$ - \$276.00



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Supplementary 1

Vehicle No : SMD2431B Case Owner : BLUECAR EAST ASIA PTE LTD
Make & Model : BLUECAR Year Manufacture : 2017
Chassis No : VL4BCEB4RJT003280 Engine No : 0
Sales Order : 0 Supplier : 0
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Item	S/N	Disposition By Surveyor
1	FRONT SUPPORT PANEL	1	\$ 420.00	\$ / 420.00			<i>Ref / Pass</i>
2	FRONT LH FENDER BEAM	1	\$ 197.00	\$ / 197.00			<i>Ref</i>
3	FRONT LH HEADLAMP FRAME	1	\$ 137.00	\$ / 137.00			<i>one</i>
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$754.00 \$ 754.00



Indeco Engineers Pte Ltd
38 Tanjong Penjuru, #04-00
CWT Logistics Hub 1,
Singapore 609039

Inventory List

Reference Number : SV21-03959
D/O Date : 14/6/2021
Vehicle No : SMD2431B
Made /Model : BlueCar
Page : 1 of 1

ACCIDENT CLAIM DEPARTMENT

S/N	Part Number	Part Description	Qty	Unit Price	Amount
1	T0461-94571	FRONT FENDER LH CS	1	\$ 1,037.00	\$ 1,037.00
2	T0960-10195	Front Wheel House Front Cover LH	1	\$ 154.00	\$ 154.00
3	NMA-00183	SCREW BRACKET M5	10	\$ 1.00	\$ 10.00
4	T1050-10391	LEFT FRONT FENDER COVER ASSY	1	\$ 194.00	\$ 194.00
5	NDEM-00664	HEX LOCKNUT M5	6	\$ 1.00	\$ 6.00
6	T0910-94915	FRONT BUMPER ASSY (WHITE)	1	\$ 1,493.00	\$ 1,493.00
7	NRIV-00685	RIVET BULBEX L.F. HEAD 15/16 OBF41 00625	10	\$ 1.00	\$ 10.00
8	T0915-00643	EXT DOOR SILL COATING LH	1	\$ 284.00	\$ 284.00
9	T0041-04333	STEEL RIM R15X6J ET38	1	\$ 254.00	\$ 254.00
10	T0023-06675	Front Shock Absorber CS LH	1	\$ 293.00	\$ 293.00
11	T0022-02331	Anti Roll Bar Tie Rod LH CS	1	\$ 105.00	\$ 105.00
12	T0026-92001	CS PILLAR LH ABS	1	\$ 400.00	\$ 400.00
13	T0025-95925	Lower Arm LH ASM (Old T0025-92101)	1	\$ 395.00	\$ 395.00
14	T0072-90383	HALF SHAFT LH ASM	1	\$ 421.00	\$ 421.00
15	T0011-94292	BONNET (HOOD) CROSSBEAM CPL US	1	\$ 420.00	\$ 420.00
16	T0420-04445	FRONT LH FENDER BEAM CPL BLUE INDY	1	\$ 197.00	\$ 197.00
17	T0921-03311	HEADLAMP LH FRAME	1	\$ 137.00	\$ 137.00

TOTAL PRICE

\$ 5,810.00

Date	Acknowledge receipt of spares	Issued by
14/6/21		T. P. L.