

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Nissan

Latio

Vehicle Number : SMS6302K

Quantity	Description	Repairer's Estimate	
	BACK		
1	REVERSE SENSOR	\$200 ✓	BR
1	RIGHT TAIL LIGHT BRACKET	\$120 X	
1	END PANEL GARNISH	\$230 182 ✓	BR
1	TAIL LAMP LOWER BRACKET	\$120 X	
1	REAR RIGHT BUMPER RETAINER (R & L)	\$180 156 ✓	
1	REAR RIGHT TAILLIGHT BRACKET	\$120 +	
1	REAR LEFT TAILLIGHT BRACKET	\$120 X	
1	REAR RIGHT WHEEL BEARING	\$150 X	
1	REAR LEFT WHEEL BEARING	\$150 X	
1	SPARE TYRE BOARD	\$80 +	
1	BOOTLID WEATHERSTRIP	\$350 148 ✓	
1	BUMPER BRACKET	\$150 X	
1	REAR RIGHT ABSORBER	\$230 +	
1	REAR LEFT ABSORBER (foam)	\$230 57 ✓	
1	REAR RIGHT MUDGUARD	\$80 X	
1	REAR LEFT MUDGUARD	\$80 X	
1	LEFT BOOTLID LAMP	\$200 X	
1	RIGHT BOOTLID LAMP	\$200 X	
1	LEFT TAIL LIGHT	\$200 X	
1	RIGHT TAIL LIGHT	\$200 +	
1	BOOT LOCK	\$350 97.90 ✓	BT
1	REAR UNDERCARRIAGE	\$900 +	
1	BOOT LID	\$1,400 787 ✓	DD
1	BOOT LID BADGE (2 pcs)	\$120 ✓	REC
1	BOOT CHROME GARNISH	\$250 X	
1	REAR BUMPER	\$650 551 ✓	BR
1	END PANEL	\$800 482 ✓	DD
	LABOUR & MISC		
1	Checking of wiring, lighting and resetting	\$300 30 ✓	
1	Remove and refit rear undercarriage	\$500 X	
1	Wheel alignment	\$100 X	
1	Remove and replace damaged parts	\$800 X	
1	Apply undercoating on repaired and replaced panel	\$800 30 ✓	

1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500 800 ✓
1	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 ✓
	Total Repair Cost :	\$12,860

Steve (LKK)
10/6/21, 9.00am

W/P
Respray After spray
L/S
6 repair days