

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 02/06/2021

Estimated repair cost for vehicle no: GT3348P TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS:JTFHT02P500245095 (2018)

10/06/2021

TPSMRT.

Hui Zhen.

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Rehd</i>	\$496.00	\$496.00 ✓
2	1	FRONT BUMPER SIDE RETAINER LH <i>Dend</i>	\$149.00	\$149.00 ✓
3	1	FRONT BUMPER REINFORCEMENT <i>Ne ne</i>	\$304.00	\$304.00 <i>x</i>
4	1	FRONT BUMPER FOG LAMP GARNISH LH <i>Ne ne</i>	\$58.00	\$58.00 <i>x</i>
5	1	FRONT BUMPER LOWER GRILLE <i>Neu</i>	\$155.00	\$155.00 <i>x</i>
6	1	LH FRONT HEADLAMP <i>Cracked</i>	\$850.00	\$850.00 ✓
8	1	LH FRONT CORNER PANEL <i>Dented</i>	\$220.00	\$220.00 ✓
9	1	LH FRONT CORNER INNER PANEL BRACKET <i>Dent</i>	\$20.00	\$20.00 ✓
10	1	BONNET <i>Dented</i>	\$750.00	\$750.00 ✓
11	1	BONNET HINGE LH <i>Ne ne</i>	\$78.00	\$78.00 <i>x</i>
12	1	WIPER TANK <i>Ne ne</i>	\$58.00	\$58.00 <i>x</i>
13	1	WIPER GARNISH LH <i>Neu</i>	\$495.00	\$495.00 <i>x</i>
14	1	LH FRONT DOOR <i>Repair</i>	\$1,700.00	\$1,700.00 <i>x</i>
15	2	LH FRONT DOOR HINGE <i>2x</i>	\$78.00	\$156.00 <i>x</i>
16	1	LH FRONT DOOR CHECKER <i>Neu</i>	\$150.00	\$150.00 <i>x</i>
17	1	FRONT GRILLE TOP <i>Cracked</i>	\$191.00	\$191.00 <i>30</i>
18	1	FRONT GRILLE BOTTOM <i>Cracked</i>	\$330.00	\$330.00 <i>2</i>
19	1	FRONT GRILLE BASE	\$490.00	\$490.00 <i>450</i>
20	1	FRONT GRILLE TOP GARNISH <i>Not nee</i>	\$150.00	\$150.00 <i>x</i>

3416

2562

TOTAL : \$6,800.00
 LESS 25 % \$1,700.00
 SUB-TOTAL : \$5,100.00

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	LH FRONT DOOR STICKER <i>Neu</i>	\$25.00	\$25.00 ✓
2	1	FRONT BUMPER CLIPS <i>Neu</i>	\$80.00	\$80.00 <i>30</i>
3	1	FRONT GRILLE CLIPS <i>Neu</i>	\$60.00	\$60.00 <i>20</i>

75

TOTAL: \$165.00

TOTAL PARTS : \$5,265.00

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 LABOUR FOR REOVE & TRANSFER FRONT LH DOORS FITTING

1370

600 \$1,000.00
~~800~~ \$800.00
30 \$80.00
40 \$200.00
x \$200.00

Subtotal :- \$2,280.00

Total:- \$7,545.00

Adrian King,
H/S 10/06/21.
05 Days.

total: 3507
H/S 3.1k

3.1k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: