



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: SALIHA SYED YUSOFF			Ref: CS3/AIG21005984/R1qf3e2-1 Date: 06/07/2021 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGD 2423X	Veh. Inspected	SKB 5245L
	Policy No.	1900010448	Coverage (\$)	0.00
	Claim No.	4150352593SG	Excess (\$)	0.00
	Assign From	SALIHA SYED YUSOFF	Assign Date	10/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200 AMG M-HYBRID	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	W1K2130802A879469	Colour	BLUE
	Odometer	4483 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R19	CONTINENTAL	6 mm
	L/H Front Tyre	245/40 R19	CONTINENTAL	6 mm
	R/H Rear Tyre	245/40 R19	CONTINENTAL	6 mm
	L/H Rear Tyre	245/40 R19	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/05/2021	Inspection Date	19/05/2021
	Survey held at	RICHMOTOR AUTO SERVICES 35 UPPER BUKIT TIMAH ROAD SHELL SERVICE STATION SINGAPORE 588166		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	