



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21006593/Vqc	
			Date: 10/06/2021	
			Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBF 2383B		Veh. Inspected	SMU 3077U
Policy No.			Coverage (\$)	0.00
Claim No.	SNM21D203289/C02/GBF2383 B/THAMYL		Excess (\$)	0.00
Assign From	PAULINE THAM		Assign Date	10/06/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/06/2021		Inspection Date	10/06/2021
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				